



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22008077/Uny3m4 Date: 02/09/2022 Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHB 5284J	Veh. Inspected	GBJ 8861C
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/08/22/2059	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	23/08/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA DYNA (M)	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JTFAT35Y60K211808	Colour	WHITE
	Odometer	142215 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195 R15	HABILEAD	6 mm
	L/H Front Tyre	195 R15	HABILEAD	6 mm
	R/H Rear Tyre	155 R12 (D/D)	HABILEAD	6/6 mm
	L/H Rear Tyre	155 R12 (D/D)	HABILEAD	6/6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	20/08/2022	Inspection Date	23/08/2022
	Survey held at	EURO SUCCESS SERVICES PTE LTD 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	