

ASS. REC. BY: T. G. J. M.

REF:

CL/CT/22008079/Inv3.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____


Insured: SLA 4085GPolicy No. DMPCSNW00055492201Claims No. SNM22D205851/C02/TOHHS

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$20K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SL41769G Yr Regn: 2024 Feb
2009, Feb.Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 320I c.c. 1995Colour: Black A/C: Insured / Std / NI / NASp. Reading: 249714 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAPG5609 ONL21520Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 Rear 6

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. 6 mm L/Bal. 6 mmD.O.A. 19/8/2022 D.O.I. 23/8/22Survey held at SpeedworksDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
30/5/23	Lump Sum \$4850 confirmed by email (red 17,415.75, 78%)

Date/Time, File Pass to?

☐ : Preli. Report1) _____
Date/Time, File Return to?☐ : Final Report2) 30/5/23-typistDays Of Repair: 5

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____
\$ + RS. \$

Photos

Others

TOTAL

Report Format: MerimenLump Sum / LBH: \$4850

SPEEDWERKZ PRIVATE LIMITED

Bartley Biz Centre 13 Kaki Bukit Road 4 #01-20 Singapore 417807

Tel: 9619 5936/ Email: info@speedwerkz.biz

VEHICLE NO: SLU1769G

MAKE & MODEL: BMW 320I

DOA: 19.08.2022

CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
REAR BUMPER	1	\$ 2,575.00	dl / 1150.20
REAR BUMPER RETAINER LH	1	\$ 125.00	nei
REAR BUMPER RETAINER RH	1	\$ 125.00	nei
REAR BUMPER LOWER GARNISH	1	\$ 725.00	dl / 273.90
REAR BUMPER BRACKET LH	1	\$ 115.00	na ins
REAR BUMPER BRACKET RH	1	\$ 115.00	na ins
REAR BUMPER REFLECTOR LH	1	\$ 225.00	X nn
REAR BUMPER REFLECTOR RH	1	\$ 225.00	X nn
REAR REINFORCEMENT	1	\$ 825.00	bt / 566
REAR REINFORCEMENT BRACKET <i>Centre bracket</i>	1	\$ 345.00	na ann / 163.50
REAR REINFORCEMENT BRACKET RH	1	\$ 345.00	X nn
REAR END PANEL	1	\$ 1,125.00	X
REAR END PANEL GARNISH	1	\$ 525.00	7 dl / 244.50
TAILLAMP LH	1	\$ 925.00	X nn
TAILLAMP RH	1	\$ 925.00	X nn
BOOTLID INNER LOCK	1	\$ 675.00	bt / 266
BOOTLID LOGO	1	\$ 180.00	nei / 60
BOOTLID EMBLEM "320I"	1	\$ 140.00	nei / 60
BOOTLID	1	\$ 2,525.00	bt / 1225.30
BOOTLID HINGES	1	\$ 120.00	X
BOOTLID LAMP LH	1	\$ 625.00	X
BOOTLID LAMP RH	1	\$ 625.00	X
EXHAUST PIPE	1	\$ 3,250.00	X
		\$ 17,385.00	
	LESS 5%	\$ 869.25	
	SUB TOTAL	\$ 16,515.75	

4489.40

4264.93.

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
REAR NUMBER PLATE	1	\$ 90.00	bt / 45
REAR BUMPER CLIP	1 SET	\$ 50.00	20 nei
REAR END PANEL TOP GARNISH CLIP	1 SET	\$ 50.00	20 nei
REVERSE SENSOR	1 SET	\$ 600.00	nei / 200
REVERSE CAMERA	1	\$ 500.00	X nn
JOINT SEALANT	1	\$ 120.00	X nn
	SUB TOTAL	\$ 1,410.00	

295

LABOUR	QTY	PRICE (\$)	REMARKS
CHECK REAR WIRING AND LIGHTING SYSTEM	1	\$ 100.00	30
REMOVE AND RENEW REAR REVERSE SENSOR	1	\$ 120.00	30
REMOVE AND RENEW REAR REVERSE CAMERA	1	\$ 120.00	X nn
REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	1	\$ 150.00	60

REMOVE AND RENEW REAR EXHAUST	1	\$ 150.00	x nn.
PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	1	\$ 1,800.00	700
SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,800.00	700
APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 100.00	30

1550

SUB TOTAL \$ 4,340.00

GRAND TOTAL \$ 22,265.75

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanf'lm 97495749 / 62563561
 WP 23/8/22 @ 325 pm
 US Resurvey after repair
 Tanf'lm C / Khando-un
 - 5 days

4264.93

295

1550

6109.93

US\$4850

- 5 days