



LCR
LION CITY RENTALS

LION CITY RENTALS PTE LTD
4 Jalan Besut S(619557)

Auto & General Insurance

Date : 22 Aug 2022

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. : SLP5691X
CHASSIS NO : JTDKB3FU103559635
MAKE / MODEL : Prius Hybrid
DATE OF ACCIDENT: 17 Jul 2022
YOUR INSURED VEHICLE NUMBER : SLT9951Z

	<u>PARTS DISCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	FRONT RH HEADLAMP <i>? Xan</i>	1PC	\$1,550.00	\$1,600.00 X
2	FRONT RH HEADLAMP RETAINER <i>? Xan</i>	1PC	\$80.00	\$80.00 X
3	FRONT BUMPER REINFORCMENT <i>Xan</i>	1PC	\$1,100.00	\$1,200.00 X
4	FRONT BUMPER <i>de</i>	1PC	\$850.00	\$850.00 <i>526</i>
5	FRONT BUMPER RH BRACKET <i>? Xan</i>	1PC	\$120.00	\$120.00 X
6	FRONT RH FOG LAMP <i>? Xan</i>	1PC	\$800.00	\$800.00 X
7	WATER TANK <i>Xan</i>	1PC	\$150.00	\$150.00 X
8	WATER TANK MOTOR <i>Xan</i>	1PC	\$180.00	\$180.00 X
9	FRONT RH FENDER LINER <i>? Xan</i>	1PC	\$700.00	\$700.00 X
10	FRONT RH FENDER <i>repair 6+</i>	1PC	\$580.00	\$580.00 ✓
11	FRONT BUMPER TOW COVER <i>MIS</i>	1PC	\$30.00	\$30.00 ✓

1136
258
852

LIST TOTAL S\$: \$6,290.00
25.00% DISCOUNT S\$: \$1,572.50
\$4,717.50

SPECIAL NETT

1 Front bumper clips *ru*

1 SET

~~\$80.00~~

30 30

Special Nett Total S\$: \$80.00

LABOUR CHARGES

1 LABOUR FOR REMOVING OUT FRONT BUMPER, RH FENDER, WATER TANK & MOTOR TO FACILITATE REPLACEMENT OF DAMAGED PARTS

~~\$1,200.00~~ 400

2 TO RESPRAY FRONT BUMPER & RH FENDER

~~\$600.00~~ 400

3 TO CHECK LIGHTING SYSTEM

~~\$100.00~~ 30 830

852
30
830
1712
208
1369.60

4/5 - \$1,350

LABOUR TOTAL S\$: \$1,900.00
TOTAL S\$: \$6,697.50
7% GST \$468.83
GRAND TOTAL S\$: \$7,166.33

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rene
Hp 90010068
3 days
4/5
24/08/22 @ 1115
Resurvey after repair