



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 6457A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BONNET	BENT	285.00	285.00
2	BONNET HINGE @\$20.00	TO REPAIR SEE LABOUR	40.00	-
1	BONNET LOGO	NECESSARY	18.00	18.00
1	FRONT BUMPER	BENT	475.00	475.00
1	AIR CON CONDENSER	BENT / PUNCTURE	250.00	250.00
1	RADIATOR AUTO	BENT	300.00	300.00
1	RADIATOR FAN COWLING	SERVICEABLE	75.00	-
1	RADIATOR FAN MOTOR	SERVICEABLE	250.00	-
1	RADIATOR FAN BLADE	SERVICEABLE	90.00	-
1	RADIATOR HOSE LOWER	SERVICEABLE	15.00	-
	COST PLUS 10%		179.80	132.80
			1,977.80	1,460.80
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET ASSORTED CLIPS (SN)	NECESSARY	80.00	60.00
			80.00	60.00
	<b><u>LABOUR</u></b>			
	TO VACUUM, RE-OIL AND RE-GAS AIR CON.		120.00	100.00
	TO REPAIR RH INNER SUPPORT PANEL INCLUDING REPLACEMENT OF PARTS. INCLUSIVE OF THE REPAIR OF BONNET HINGE.		600.00	400.00
	TO SPRAY PAINT ON BONNET, FRONT BUMPER, RH INNER SUPPORT.		700.00	600.00
			1,420.00	1,100.00
	<b>GRAND TOTAL</b>		<b>3,477.80</b>	<b>2,620.80</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>2,620.80</b>

Report Ref No. CS/UOI22008087/Kqy3e2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.