



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI22008087/Kqy3e2	
			Date: 29/09/2022	
			Code: UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMK 8585P	Veh. Inspected	GBJ 6457A
	Policy No.		Coverage (\$)	0.00
	Claim No.	M12D19342209	Excess (\$)	0.00
	Assign From	JOSEPHINE WONG	Assign Date	23/08/2022
2. Vehicle Particulars & Condition				
	Make & Model	SUZUKI EVERY (A)	c.c	658
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	DA17V261198	Colour	WHITE
	Odometer	50773 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	155 R12X8	YOKOHAMA	7 mm
	L/H Front Tyre	155 R12X8	YOKOHAMA	7 mm
	R/H Rear Tyre	155 R12X8	DUNLOP	6 mm
	L/H Rear Tyre	155 R12X8	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	22/08/2022	Inspection Date	24/08/2022
	Survey held at	FALCON-AIR AUTO SERVICES PTE LTD (HQ) 176 SIN MING DRIVE #01-06/07/13, SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	