

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	STRIDES AUTOMO	OTIVE SERVICES PTE LTD		Ref:	CS/SMR22008089/Kvy3m4	
	60 WOODLANDS I E4SINGAPORE 75	NDUSTRIAL PARK 7705		Date:	07/09/2022	
				Code:	SMR	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHC 4988M	Veh. Inspected		FBG 48C	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	TAX/08/22/2052	Excess (\$)		0.00	
	Assign From	HUA YEN	Assign Date		23/08/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	HONDA CBR400	c.c		399	
	Engine No.	HIDDEN	Year of Reg.		2013	
	Chassis No.	NC471003561	Colour		BLACK	
	Odometer	41430 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	120/70 ZR17	PIRELLI		3 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	160/60 ZR17	PIRELLI		3 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	19/08/2022	Inspection Dat	е	24/08/2022	
	Survey held at	SG 98 MOTOR PTE LTD				
		BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		2 Worki	ng Days	