



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF22008090/Rwy3m4
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1 HEMMANT ROAD SINGAPORE 438675		Date:	17/05/2023
ATTN: HAFIZUL FARHAN		Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	QX 691C	Veh. Inspected	SLD 564B
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2022/051	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	23/08/2022
2. Vehicle Particulars & Condition			
Make & Model	MAZDA 6 4-DR SEDAN 2.0L SP	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JM6GJ1072G0237839	Colour	WHITE
Odometer	173541 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/55 ZR17	KUMHO	6 mm
L/H Front Tyre	225/55 ZR17	KUMHO	6 mm
R/H Rear Tyre	225/55 ZR17	KUMHO	6 mm
L/H Rear Tyre	225/55 ZR17	KUMHO	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	26/04/2022	Inspection Date	16/11/2022
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	