

# Vin's

**Vin's Motor Pte Ltd**  
160 Sin Ming Drive  
#03-03 Sin Ming Autocity  
Singapore 575722  
Tel : 6453 2121 Fax : 6459 9795  
GST Registration No. 199906067G

## Estimated Cost of Repair

**Attention To :** NTUC Income Insurance Co-operative Ltd  
75 Bras Basah Road  
#05-00 NTUC Income Centre  
Singapore 189557

### Claim Details

**Case Ref. No. :** TP  
**Date :** 03-08-2022  
**Accident Date :** 24-07-2022

### Vehicle Details

**Make & Model :** Honda FIT HYBRID 1.5 AUTO  
**Chassis No :** GP51340192  
**Registration No :** SBG3232S

### Third Party Vehicle Details

**Registration No :** SJT5665A

S/N	Description	Qty	Amount (\$)
1	REAR BUMPER / LKA	1.00	\$529.80
2	REAR BUMPER LOWER PAD CENTER / HA	1.00	\$65.80
3	REAR BUMPER CLIPS @\$4.20 / MC	10.00	\$42.00
			\$637.60
<b>Discount: -20%</b>			(\$127.52)
			\$510.08
4	REAR BUMPER SENSOR / RM	1.00	\$280.00
5	TO REPAIR DAMAGE	1.00	\$380.00
6	TO SPRAY PAINTING	1.00	\$380.00
<b>Subtotal w/o GST:</b>			\$1,550.08

2-3 Days.  
P/P  
refer with photos  
Gene Ong  
23/8/22

200  
300  
350

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Issued by Elaine Lee

This is a computer-generated document. No signature is required.