



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC22008098/Gny3e2

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

Date: 01/02/2023

ATTN: RODERIC YUEN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBP 1191S	Veh. Inspected	SLM 2051D
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1185019-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	23/08/2022

2. Vehicle Particulars & Condition

Make & Model	TOYOTA SIENTA 1.5G	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	NSP1707013571	Colour	BLACK
Odometer	117750 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm
L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/08/2022	Inspect Date / Time	23/08/2022 (11:00 AM)
Survey held at	VIN'S MOTOR PTE LTD 160 SIN MING DRIVE #03-03 SIN MING AUTO CITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**