

Estimated Cost of Repair

Claim Details

Case Ref. No. : TP/082022/5590

Vin's Motor Pte Ltd 160 Sin Ming Drive #03-03 Sin Ming Autocity Singapore 575722 Tel: 6453 2121 Fax: 6459 9795 GST Registration No. 199906067G

Date : 22-08-2022 Accident Date : 19-08-2022

**Vehicle Details** 

**Attention To** 

Make & Model : Toyota SIENTA 1.5G CVT

operative Ltd

75 Bras Basah Road

Singapore 189557

**NTUC Income Insurance Co-**

#05-00 NTUC Income Centre

 Chassis No
 : NSP1707013571

 Registration No
 : SLM2051D

Third Party Vehicle Details

Registration No : FBP1191S

S/N	Description	Qty	Amount (S\$)
1	REAR TAILGATE	1.00	\$1,199.60
2	REAR TAILGATE RH REFLECTOR	1.00	\$277.50
3	REAR TAILGATE RUBBER	1.00	\$394.70
4	REAR TAILGATE WINDSCREEN MOULDING	1.00	\$32.80
5	REAR RH TAILLAMP	1.00	\$398.20
5	REAR BUMPER / CC	1.00	\$337.30
7	REAR BUMPER RH PROTECTOR	1.00	\$136.80
3	REAR BUMPER SENSOR / PM	1.00	\$275.90
9	REAR BUMPER RH SIDE RETAINER / BC	1.00	\$74.70
10	REAR RH SUIDING DOOR PROTECTOR	1.00	\$65.50
1	REAR RH SLIDING DOOR PROTECTOR	, 1.00	\$118.60
12	REAR RH SPORT RIM  Cut ( total 150.	Refri	(SC)\$415.80
	•		\$3,727.40
		Discount: -25%	(\$931.85)
3	WINDSCREEN GUM / MCC	4.00	\$2,795.55
ı	TO CHECK WHEEL ALIGNMENT	1.00	\$80.00
5	TO REMOVE AND REFIX TAILGATE GLASS	1.00	\$150.00
3	TO REPAIR DAMAGES	1.00	\$180.00
7	TO SPRAY PAINTING	1.00	\$780.00
		1.00	\$980.00
	6 1/cm S	btotal w/o GST:	\$4,965.55

122 SC P

## Issued by Iswan

This is a computer-generated document. No signature is required.

22/8/22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary stemper must be resurveyed <u>and</u> is subject to face conduct from իրչերգինе Company

Acknowless sugar