

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
 ROC/ GST Reg No.: 200007407G

Date: 21 Aug 2022

ASSESSMENT FOR REPAIR: YAMAHA SNIPER T150 - FBM7064C

Chassis No.:

Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front disk	\$115.00 <i>34t</i>
1 pc	Front wheel axle	\$75.00 <i>747</i>
1 pc	Right fork assembly	\$380.00 <i>bt</i>
1 pc	Left fork assembly	\$380.00 <i>bt</i>
1 pc	Front headlamp lower cover	\$105.00 <i>cut</i>
1 pc	Headlamp lower assy	\$250.00 <i>cut</i>
1 pc	Front mudguard	\$85.00 <i>mis</i>
2 pcs	Steering stem bearing @ \$45.00	\$90.00 <i>rel</i>
1 pc	Steering stem bracket assembly	\$195.00 <i>bt</i>
1 pc	Gear pedal assembly	\$105.00 <i>bt</i>
1 pc	Left front footrest	\$65.00 <i>bru</i>
1 pc	Left front signal	\$75.00 <i>cut</i>
1 pc	Handle bar	\$125.00 <i>747</i>
1 pc	Right fairing	\$105.00 <i>cut</i>
1 pc	Left fairing	\$105.00 <i>cut</i>
2 pcs	Fairing stickers @ \$55.00	\$110.00 <i>rel</i>
1 pc	Right front signal	\$75.00 <i>nn</i>
1 pc	Brake pedal assy	\$75.00 <i>nn</i>
1 pc	Front black cover back	\$125.00 <i>cut</i>
1 pc	Front footrest holder assembly	\$145.00 <i>747</i>
1 pc	Clutch lever	\$45.00 <i>cut</i>
1 pc	Left balancer	\$45.00 <i>mis</i>
1 pc	Right balancer	\$45.00 <i>mis</i>
1 pc	Front cover labels	\$35.00 <i>rel</i>
1 pc	Top head cover	\$75.00 <i>cut</i>
1 pc	Front headlamp	\$145.00 <i>cut</i>
1 pc	Front head inner black cover	\$125.00 <i>cut</i>
1 pc	Left rear side cover	\$105.00 <i>cut</i>
1 pc	Left rear side cover sticker	\$45.00 <i>cut</i>
1 pc	Right rear footrest	\$45.00 <i>cut</i>
1 pc	Left view mirror	\$45.00 <i>mis</i>
1 pc	Right view mirror	\$55.00 <i>cut</i>
1 pc	Exhaust assembly	\$485.00 <i>747</i>
<i>Full unit cut</i>		
	Less discount 10%	\$4,080.00
		\$408.00
		\$3,672.00
<u>Special nett items</u>		
1 pc	Front number plate	\$20.00 <i>cut</i>
1 pc	Top box	\$195.00 <i>cut</i>
1 pc	Box bracket	\$145.00 <i>cut</i>
1 pc	Front tyre	\$110.00 <i>q-nn</i>
1 pc	Front sport rim assy	\$380.00 <i>bt</i>

3685
 10% 3316.50
 595

- | | | |
|----|--|--------------------------|
| 1) | Towing charges | \$100.00 ✓ |
| 2) | Dismantle, replace, realign and adjust above damaged parts | \$700.00 300 |
| 4) | To knock, straighten chassis & body balancing | \$380.00 ✗ nm |
| 5) | To remove/refit, replace (if damage) check and straighten front fork tubes | \$180.00 120 photo? |
| 6) | To remove/refit and balance front sport rim | \$90.00 30 |
| 7) | Spray painting | \$300.00 200 |

Total Estimate

\$6,272.00

750

Note: The above estimate is subjected to the prevailing GST of 7%

Taufik 97495746
 wpr 23/8/22 @ 150pm
 4/5 spray after repair
 Taufik @ khantow
 3 days + 4 days

For Bike Production Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
 ROC/ GST Reg No.: 200007407G

Date: 30 Aug 2022

SUPPLEMENTARY FOR REPAIR: YAMAHA SNIPER T150 - FBM7064C

Chassis No.:

Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	IU bracket	\$35.00 <i>ht</i>
1 pc	Right front footrest	\$65.00 <i>my</i>
1 pc	Left engine cover	\$195.00 <i>dd</i>
1 pc	Gasket	\$45.00 <i>ul</i>
1 pc	Right fairing lower cover	\$75.00 <i>tn</i>
1 pc	Front cover	\$95.00 <i>art</i>
1 pc	Rear mudguard assembly	\$185.00 <i>cu</i>
2 pcs	Yamaha ambler @ \$20.00	\$40.00 <i>ue</i>
1 pc	Rear handdle	\$45.00 <i>at</i>
1 pc	H cover	\$50.00 <i>de</i>
1 pc	Left rear footrest holder	\$65.00 <i>del</i>
1 pc	Radiator assy	\$195.00 <i>bt</i>
1 pc	Rear handle bar	\$55.00 <i>xentat</i>
1 pc	Headlamp bracket	\$95.00 <i>bt</i>
1 pc	Tailcover	\$45.00 <i>de</i>
		\$1,285.00 <i>1285</i>
	Less discount 10%	\$128.50 <i>1156.50</i>
		\$1,156.50
	<u>Special nett items</u>	
1 pc	ERP IU	\$157.00 <i>art</i>
1 pc	Engine oil	\$30.00 <i>ue</i>
1 pc	Coolanr	\$48.00 <i>nec</i>
1 pc	Food bag	\$75.00 <i>m</i> <i>310</i>
1)	Labour for supplementary items work	\$200.00 <i>100</i>
	Total Estimate	
		\$1,666.50

Note: The above estimate is subjected to the prevailing GST of 7%

Taykhi
11/9/22 @ 340

3316.50

595

750

1156.50

320

100

6228

04 days

4549.50



LKK Auto Consumers will notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____