

ASS. REC BY: Tou J M

REF: CS/INC 22008099/Ty 3

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated cost: \_\_\_\_\_  
 OD / TP / IS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: FBM 7064C Yr Regn: 2018, March  
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Yamaha Sniper 150 C.C. 150  
 Colour: Blue A/C: Insured / Std / NI / NA  
 Sp. Reading: - T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: MH346 0740400 67219  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 80/90R17  
 R: 120/70R17  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  

N/S	O/S

  
 Bal. or Market Value: 99000  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 5 mm R/Bal. 5 mm  
 L/Bal. \_\_\_\_\_ mm L/Bal. \_\_\_\_\_ mm  
 D.O.A. \_\_\_\_\_ D.O.I. 23/8/22  
 Survey held at Bike Production  
 Des. of Damages: Fr / Rear / C/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 1) \_\_\_\_\_  
 Date/Time, File Return to?  
 2) \_\_\_\_\_  
 Rep. Form: \_\_\_\_\_  
 Lapse Sum / L. B. / C.

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_  
 Add Fee:  : Site Insp (\$) )  
 : Interview (\$) )  
 : Tech. invs (\$) )  
 : Weekend (\$) )  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 S + RS. \$ \_\_\_\_\_  
 Photos \_\_\_\_\_  
 Others \_\_\_\_\_  
 TOTAL \_\_\_\_\_

**BIKE PRODUCTION PTE LTD**  
 610, Serangoon Road S(218216)  
 Tel: 63922555, 62995177 Fax: 62975400  
**ROC/ GST Reg No.: 200007407G**

Date: 21 Aug 2022

ASSESSMENT FOR REPAIR: YAMAHA SNIPER T150 - FBM7064C

Chassis No.:


Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front disk	\$115.00 ?
1 pc	Front wheel axle	\$75.00 ?
1 pc	Right fork assembly	\$380.00 <i>bt</i> -
1 pc	Left fork assembly	\$380.00 <i>bt</i> -
1 pc	Front headlamp lower cover	\$105.00 <i>cut</i> -
1 pc	Headlamp lower assy	\$250.00 <i>cut</i> -
1 pc	Front mudguard	\$85.00 <i>mis</i> ✓
2 pcs	Steering stem bearing @ \$45.00	\$90.00 <i>rel</i> -
1 pc	Steering stem bracket assembly	\$195.00 <i>bt</i> -
1 pc	Gear pedal assembly	\$105.00 <i>bt</i> -
1 pc	Left front footrest	\$65.00 <i>bro</i> ✓
1 pc	Left front signal	\$75.00 <i>cut</i> -
1 pc	Handle bar	\$125.00 ?
1 pc	Right fairing	\$105.00 <i>cut</i> -
1 pc	Left fairing	\$105.00 <i>cut</i> -
2 pcs	Fairing stickers @ \$55.00	\$110.00 <i>rel</i> -
1 pc	Right front signal	\$75.00 X
1 pc	Brake pedal assy	\$75.00 X
1 pc	Front black cover back	\$125.00 <i>cut</i> - ?
1 pc	Front footrest holder assembly	\$145.00 ?
1 pc	Clutch lever	\$45.00 <i>cut</i> -
1 pc	Left balancer	\$45.00 <i>mis</i> ✓
1 pc	Right balancer	\$45.00 <i>mis</i> ✓
1 pc	Front cover labels	\$35.00 <i>rel</i> -
1 pc	Top head cover	\$75.00 <i>cut</i> -
1 pc	Front headlamp	\$145.00 X
1 pc	Front head inner black cover	\$125.00 <i>cut</i> -
1 pc	Left rear side cover	\$105.00 <i>cut</i> -
1 pc	Left rear side cover sticker	\$45.00 <i>cut</i> -
1 pc	Right rear footrest	\$45.00 X
1 pc	Left view mirror	\$45.00 <i>mis</i> ✓
1 pc	Right view mirror	\$55.00 X
1 pc	Exhaust assembly	\$485.00 * ?
	<i>Full unit cut</i> ✓	
	Less discount 10%	\$4,080.00
		\$408.00
		<u>\$3,672.00</u>
	<b><u>Special nett items</u></b>	
1 pc	Front number plate	\$20.00 <i>cut</i> -
1 pc	Top box	\$195.00 <i>cut</i> -
1 pc	Box bracket	\$145.00 X
1 pc	Front tyre	\$110.00 X
1 pc	Front sport rim assy	\$380.00 <i>bt</i> -

1)	Towing charges	\$100.00 ✓
2)	Dismantle, replace, realign and adjust above damaged parts	\$700.00 300
4)	To knock, straighten chassis & body balancing	<del>\$380.00 X</del>
5)	• To remove/refit, replace (if damage) check and straighten front fork tubes	\$180.00 (20 photo?)
6)	To remove/refit and balance front sport rim	\$90.00 30
7)	Spray painting	\$300.00 200
	<b>Total Estimate</b>	<u>\$6,272.00</u>

Note: The above estimate is subjected to the prevailing GST of 7%

Taufik 97495749  
 WP 23/8/22 @ 150 pm  
 4/3 Resray after repair  
 Taufik @ khantowan  
 3 days - 4 days

*[Handwritten signature]*  
  
 For Bike Production Pte Ltd

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_