



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|---|---|------------|
| INCOME INSURANCE LTD 75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557 ATTN: NATALIE LEE | | | Ref: CS/INC22008099/Tcy3q2 Date: 06/12/2022 Code: INC | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | AN 1332A | Veh. Inspected | FBM 7064C |
| | Policy No. | | Coverage (\$) | 0.00 |
| | Claim No. | MT/1152078- 002 | Excess (\$) | 0.00 |
| | Assign From | HAZALYSA BINTE IBRAHIM | Assign Date | 23/08/2022 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | YAMAHA SNIPER T150 | c.c | 150 |
| | Engine No. | HIDDEN | Year of Reg. | 2018 |
| | Chassis No. | MH34G074040067219 | Colour | BLUE |
| | Odometer | - | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | NIL |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 80/90 R17 | PIRELLI | 5 mm |
| | L/H Front Tyre | | | mm |
| | R/H Rear Tyre | 120/70 R17 | PIRELLI | 5 mm |
| | L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION , O/S AND N/S BODY. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 22/11/2021 | Inspection Date | 23/08/2022 |
| | Survey held at | BIKE PRODUCTION PTE LTD 610 SERANGOON ROAD SINGAPORE 218216 | | |
| 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 4 Working Days | |