

D.O.A. : 19/8/2022

TSL Auto Garage

Estimate

PAGE : 1/2

YEAR : 2021 VEHICLE NO : GBL4450X
 MODEL : NISSAN NV200 1.6 (A) PETROL CHASSIS NO : JN1YAAM20Z0002351

Third Party Claims

S/NO	ITEMS	Qty	Price	
1	REAR BUMPER	1	de ✓ \$520.00	481
2	REAR BUMPER SIDE RETAINER	2	de ✓ \$220.00	178
3	REAR BUMPER SPONGE	1	cnr ✓ \$210.00	121
4	REAR BUMPER TOWING CAP	1	x ✓ \$95.00	50
5	REAR TAILGATE	1	bt ✓ \$1,920.00	1795
6	REAR TAILGATE NUMBER PLATE GARNISH	1	x ✓ \$320.00	
7	REAR TAILGATE LOCK	1	bt ✓ \$420.00	332
8	REAR TAILGATE INNER TRIM	1	ny ✓ \$320.00	242
9	REAR TAILGATE EMBLEM "NISSAN"	1	ner ✓ \$195.00	103
10	REAR TAILGATE EMBLEM "NV200"	1	ner ✓ \$135.00	60
11	REAR TAILGATE DAMPER	2	x ✓ \$440.00	
12	REAR TAILGATE HINGE	2	x ✓ \$220.00	
13	REAR TAILGATE OUTER HANDLE	1	x ✓ \$330.00	244
14	REAR WIPER MOTOR	1	x ✓ \$420.00	
15	REAR TAIL LAMP @ 277	2	cnr ✓ \$660.00	554
16	REAR END PANEL - INNER	1	bt ✓ \$620.00	} 640
17	REAR END PANEL - OUTER	1	bt ✓ \$490.00	
18	REAR END PANEL TOP GARNISH	1	de ✓ \$195.00	124
19	REAR SPARE TYRE CARRIER	1	bt ✓ \$320.00	285
20	REAR SPARE TYRE CARRIER LOCK	1	x ✓ \$110.00	
21	REAR FLOOR PANEL	1	Ry ✓ \$2,290.00	\$200
22	REAR FENDER INNER TRIM	2	x ✓ \$660.00	
23	WEATHERSHIP	1	de ✓ \$185.00	118
24	REAR WINDSCREEN MOULDING	1	ner ✓ \$110.00	
25	REAR EXHAUST ASSY	1	x ✓ \$790.00	
			\$12,195.00	
		Discount 10%	\$1,219.50	
		TOTAL :	\$10,975.50	

S/NO	SPECIAL ITEMS	Qty	Price
1	REAR BUMPER CLIPS	1SET	30ner ✓ \$50.00
2	REAR BUMPER REVERSE SENSOR	1SET	200 ✓ \$250.00
3	REAR BUMPER TOP PROTECTOR - BLACK	1	de ✓ \$200.00
4	REAR TAILGATE INNER TRIM CLIPS	1SET	20 ✓ \$50.00
5	REAR END PANEL TOP CLIPS	1SET	10 ✓ \$50.00
6	SEALANT	1	40 ✓ \$50.00

7	STICKER "70KM/H"	1	net — \$50.00 20
8	STICKER "6PAX"	1	net — \$50.00 20
9	COMPANT STICKER	1	net — \$500.00 300
			\$1,250.00
		Parts Total :	\$10,975.50
		S/P Item :	\$1,250.00
		TOTAL :	\$12,225.50

TSL Auto Garage

Estimate

PAGE : 2/2

YEAR : 2021 VEHICLE NO : GBL4450X
MODEL : NISSAN NV200 1.6 (A) PETROL CHASSIS NO : JN1YAAM20Z0002351

S/NO	LABOURS	AMOUNT
1	To straighten and panel beat rear frame members, to cut/weld and remove and refit above parts.	\$ 1000 2,000.00
2	To putty, re-spray painting and polish rear affected areas.	\$ 900 2,000.00
3	To rust proof affected areas.	\$ 30 100.00
4	To check and rectify wiring.	\$ 30 100.00
5	To remove and refit bumper sensor.	\$ 30 100.00
6	To remove and refit rear windscreen glass.	\$ 120 150.00
7	To conduct diagnostic systems and to clear faults code.	\$ X 200.00
8	To remove and refit rear floor board assy in order to works.	\$ 40 300.00
9	To remove and refit upholstery, seats and inner trim boards.	\$ 60 300.00

NOTE: ALL QUOTED PRICE IS SUBJECT TO 7% GST

TOTAL : \$ 5,250.00
PARTS TOTAL : \$ 12,225.50
GRAND TOTAL : \$ 17,475.50

Taufik 97495749
'WP' 24/8/22
cls Rising after repair
taufik@khando.com
7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: