

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0718/2022/EQ
DATE : 20-Aug-22
WIP : 38198

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/8/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. ONG KIAN HONG
ADDRESS : 76 GILSTEAD ROAD
SINGAPORE 309114
TELEPHONE : HP +65 96646745
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100233873-10
VEHICLE NO : **SJZ 348 S**
MODEL CODE : AUDI A4 1.8T FSI MU
MODEL YEAR : 22/10/2010
ENGINE NO : CDH 092423
CHASSIS NO : WAUZZZ8K0AA163313
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Aug-22
PLACE OF ACCIDENT : NEAR TRAFFIC JUNCTION OF VELOCITY
(NOVENA)/NEWTON ROAD

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJZ 348 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00 x	
2	TO REMOVE AND TRANSFER RHS FRONT DOOR 'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00 280 ✓	
3	TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW RHS FRONT FENDER AND RHS FRONT DOOR. TO REPAIR RHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,800.00 750 ✓	3 x 550 = 1650 Mirror = 120
4	TO RESPRAY RHS FRONT FENDER, RHS FRONT DOOR, RHS SILL PANEL AND RHS WING MIRROR COVER.	\$ 3,500.00	
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00 ✓	1720 ✓
TOTAL LABOUR CHARGES		: \$ 7,252.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJZ 348 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT FENDER - RH <i>Repair</i>	1	\$ 1,111.00	<i>x</i>
2	REAR FENDER BRACKET - RH <i>New</i>	1	\$ 55.00	<i>x</i>
3	FRONT WHEEL HOUSING LINER <i>New</i>	1	\$ 260.00	<i>x</i>
4	FRONT DOOR - RH <i>Dented</i>	1	\$ 4,175.00	<i>✓</i> 3340
5	FRONT OUTER DOOR SEAL <i>New</i>	1	\$ 229.00	<i>✓</i> 182.80
6	BONDING AGENT <i>? nn</i>	1	\$ 51.00	<i>?</i> <i>x</i>
7	CLEANING SOLUTION <i>? nn</i>	1	\$ 74.00	<i>?</i> <i>x</i>
8	APPLICATOR <i>? nn</i>	1	\$ 9.00	<i>?</i> <i>x</i>
9	FRONT DOOR CATCH <i>? nn</i>	1	\$ 134.00	<i>?</i> <i>x</i>
10	SHOULDERED BOLT <i>New</i>	2	\$ 73.00	<i>x</i>
11	FRONT WING MIRROR MOUNTING - RH <i>New</i>	1	\$ 1,479.00	<i>✓</i> 1183.20
12	FRONT WING MIRROR CAP - RH <i>New</i> <i>? cracked</i>	1	\$ 627.00	<i>?</i> 501.60
13	FRONT WING MIRROR GLASS - RH <i>New</i>	1	\$ 1,776.00	<i>x</i>
14	FRONT TURN SIGNAL INDICATOR <i>? nn</i>	1	\$ 111.00	<i>?</i> <i>x</i>
15	FRONT TYRE PRESSURE DATA PLATE <i>? nn</i>	1	\$ 34.00	<i>?</i> <i>x</i>
16	STONE CHIP <i>? nn</i>	S/N	\$ 180.00	<i>?</i> <i>x</i>
17	SUNDRIES <i>? nec</i>		\$ 400.00	<i>?</i> 26.96
TOTAL SPARE PARTS		:	\$ 10,778.00	
TOTAL LABOUR CHARGES		:	\$ 7,252.00	
GRAND TOTAL		:	\$ 18,030.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj* *SJZ 348S*
 SURVEYED DATE : *23/08/22*
 AUTHORISED DATE :
 EXCESS COST :
 LIABILITY :
 REMARKS : *Not Authorised, 05 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT