



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INCOME INSURANCE LTD 75 BRAS BASAH ROAD INCOME CENTRE SINGAPORE 189557 ATTN: AZHARI AFIDI			Ref: CS/INC22008113/Acy3e2 Date: 14/11/2022 Code: INC	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMP 4138Y	Veh. Inspected	SLF 102R	
Policy No.		Coverage (\$)	0.00	
Claim No.	MT/1185116-003	Excess (\$)	0.00	
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	23/08/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA SIENTA	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	NSP1707006041	Colour	BLUE	
Odometer	257340 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	TRIANGLE	6 mm	
L/H Front Tyre	185/60 R15	TRIANGLE	6 mm	
R/H Rear Tyre	185/60 R15	TRIANGLE	6 mm	
L/H Rear Tyre	185/60 R15	TRIANGLE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/08/2022	Inspection Date	23/08/2022	
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			14 Working Days	