



UCB Engineering Pte Ltd

Business Reg. No. 199501338G

Our ref. 220803.WX(PC668D)

29 August 2022

Wei Xing Travel Pte Ltd
34 Craig Road
Singapore 089673

QUOTATION
without Prejudice

Dear Sir,

COST OF REPAIR FOR PA 668 D

QTY	DESCRIPTIONS	PRICE S\$
1 pc	RHS panel <i>x R</i>	2,050.00
1 pc	Rear lamp - RH <i>OR</i>	285.00
1 pc	Rear bumper cover - RH <i>OR CRA</i>	205.00
1 pc	Rear bumper <i>OR</i>	680.00
	Labour charges for dismantle & assemble window glass X 2	400.00 <i>X</i>
	Labour charges for remove & replace the above damaged Part	1,800.00 <i>800</i>
	To putty & spray painting onto affected areas	1,000.00 <i>800</i>
	Wiring charges	30.00 <i>/</i>
	TOTAL	6,450.00 =====

(SGD: Six Thousand Four Hundred and Fifty Only)

Yours faithfully,
Tan Tiong Chia

Steve (LKK) 83728813

8/9/22, 11.00am

m R

5 dgs

L/S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2C Jalan Pesawat, Jurong, Singapore 619359

Tel : 6268 1281

E-mail : unitedcb@singnet.com.sg