



UCB Engineering Pte Ltd

Business Reg. No. 199501338G

Our ref: 220803.WX(PC668D)

29 August 2022

Wei Xing Travel Pte Ltd
34 Craig Road
Singapore 089673

QUOTATION
without Prejudice

Dear Sir,

COST OF REPAIR FOR PA 668 D

QTY	DESCRIPTIONS	PRICE S\$	
1 pc	RHS panel <i>x R</i>	2,050.00	
1 pc	Rear lamp - RH <i>OR</i>	285.00 ✓	
1 pc	Rear bumper cover - RH <i>OR CRA</i>	205.00 170 ✓	1135
1 pc	Rear bumper <i>OR</i>	680.00 ✓	-25% 851.25
	Labour charges for dismantle & assemble window glass X 2	400.00 X	
	Labour charges for remove & replace the above damaged Part	1,800.00 800	
	To putty & spray painting onto affected areas	1,000.00 800	
	Wiring charges	30.00 ✓	
	TOTAL	6,450.00	1630
		=====	

(SGD: Six Thousand Four Hundred and Fifty Only)

Yours faithfully,
Tan Tiong Chia

Steve (LKK) 83728813

8/9/22, 11.00am

m R

5 d/s

L/S

2481.25

L/S - 1985
= 2000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2C Jalan Pesawat, Jurong, Singapore 619359

Tel : 6268 1281

E-mail : unitedcb@singnet.com.sg