

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Mindef ref: CY22/MID59065/180822/0031

LKK ref: CC2/MIDA22008114/Ep Date: 13.09.2022

HQ TRANSPORT COMMAND

Attn: Maj Edwin

Dear Sir/Madam

APPRAISAL OF DAMAGED VEHICLE BEFORE REPAIRS: PA 668D

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on

8/9/2022 at the premises of M/s UCB ENGINEERING PTE LTD


and have the following to report:-

Workshop Estimate Amount	: S\$	6,450.00
Revised Estimate Amount	: S\$	2,800.00
"Check" Items Amount	: S\$	
Total	: S\$	2,800.00
Market Value	: S\$	(est)
LTA Reimbursement Value	: S\$	(est)
Nett Value	: S\$	- (est)

Description of Damage:

The vehicle sustained damages at the

REAR RIGHT SIDE



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

STEVE CHEN

Licensed Appraiser