



# UCB Engineering Pte Ltd

Business Reg. No. 199501338G

Our ref: 220803.WX(PA668D)

Your ref:

17 April 2023

LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1  
#01-25 Paya Ubi Industrial Park  
Singapore 408933  
Attn : Miss Hsiao Tong

**without Prejudice**  
chewht@lkkauto.com

Dear Sirs

## **ACCIDENT INVOLVING PA 668 D AND 59065MD ON 18/08/2022 ALONG UPPER CHANGI ROAD EAST**

We refer to the above matter.

After survey by your surveyor and repaired, we are now instructed to claim as follow:

1)	Cost of repair	\$2,000.00
2)	Loss of use 5 days x \$250/-	\$1,250.00
	<b>Total</b>	<b>\$3,250.00</b>

We enclose the following:

a) Repair bill

Kindly let us have your offer as soon as possible.

Yours faithfully

**Tan Tiong Chia**



# UCB Engineering Pte Ltd

Business Reg. No. 199501338G

Bill To :

Wei Xing Travel Pte Ltd  
34 Craig Road  
Singapore 089673

**INVOICE NO : T-220803**

Date : 10-Apr-23

**Payment Term : COD**

Our D/O No : \_\_\_\_\_

Your P/O No : \_\_\_\_\_

**Vehicle No** : PA 668 D

DESCRIPTION	QTY	UNITS	UNIT PRICE	AMOUNT
Rear bumper	1			
Rear bumper cover	1			\$ 2,000.00
Rear lamp - RH	1			
Labour charges for remove & replace the above damagghed parts	1			
To putty & spray painting onto affecteder areas	1			
Wiring charges.	1			
			Lump Sum	\$ 2,000.00

\* Please notify us of any discrepancy within 7 days  
of invoicing

\* Cheque should be crossed and made payable to  
UCB ENGINEERING PTE LTD

for ucb engineering pte ltd

*Authorised Signature*