



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBR 90X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	NOT NECESSARY	1,450.00	-
1	FRONT BUMPER SIDE RETAINER	NOT NECESSARY	95.00	-
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	975.60	-
1	FRONT FENDER INNER GARNISH RH	NOT NECESSARY	95.30	-
1	FRONT FENDER LOWER GARNISH RH	NOT NECESSARY	87.30	-
1	FRONT FENDER COWLING RH	NOT NECESSARY	249.40	-
1	FRONT DOOR VIEW MIRROR COVER RH	NOT NECESSARY	988.00	-
1	FRONR DOOR RH	TO REPAIR SEE LABOUR	1,988.90	-
1	FRONT DOOR OUTER MOULDING RH	NOT NECESSARY	174.80	-
1	FRONT DOOR REGULATOR RH	NOT NECESSARY	275.40	-
1	FRONT DOOR FRAME WEATHERSTRIP RH	NOT NECESSARY	289.80	-
1	FRONT DOOR LOWE GARNISH RH	NOT NECESSARY	780.90	-
1	ROCKER PANEL RH	NOT NECESSARY	326.70	-
1	SLIDING DOOR RH	NOT NECESSARY	1,496.50	-
1	SLIDING DOOR PROTECTOR RH	NOT NECESSARY	1,154.30	-
1	REAR FENDER PROTECTOR RH	NOT NECESSARY	292.70	-
1	REAR BUMPER	NOT NECESSARY	590.60	-
2	REAR BUMPER SIDE RETAINER @\$69.70	NOT NECESSARY	139.40	-
	LESS 25% DISCOUNT		-2,862.65	-
			8,587.95	-
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT DOOR SEALANT RH (SN)	NOT NECESSARY	60.00	-
1	SET FRONT DOOR PROTECTOR CLIPS RH (SN)	NOT NECESSARY	30.00	-
1	SET FRONT DOOR INNER TRIM CLIPS RH (SN)	NOT NECESSARY	60.00	-
1	SLIDING DOOR SEALANT RH (SN)	NOT NECESSARY	60.00	-
1	SET SLIDING DOOR STEP GARNISH CLIP RH (SN)	NOT NECESSARY	40.00	-
1	SET SLIDING DOOR INNER TRIM CLIP RH (SN)	NOT NECESSARY	60.00	-
1	SET SLIDING DOOR STEP PANEL GARNISH CLIP RH (SN)	NOT NECESSARY	40.00	-
1	SET REAR FENDER COWLING CLIP RH (SN)	NOT NECESSARY	60.00	-

Report Ref No. CS/INC22008117/Avy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR BUMPER CLIP RH (SN)	NOT NECESSARY	50.00	-
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
			510.00	-
	LABOUR			
	PANEL BEATING, REMOVAL AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER RH AND FRONR DOOR RH.		2,400.00	100.00
	TO SPRAY PAINT AFFECTED AREA.		2,100.00	500.00
	TO PERFORM LIGHTING & WIRING CHECK.	NOT NECESSARY	120.00	-
	TO APPLY ANTI-RUST & TUFF KOTE.	NOT NECESSARY	250.00	-
	TRANSFER FRONT AND REAR DOOR MECHANISM.	NOT NECESSARY	420.00	-
	TO CHECK FOUR WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	RESET ABS LIGHT.	NOT NECESSARY	320.00	-
			5,730.00	600.00
GRAND TOTAL			14,827.95	600.00
RECOMMENDED COST OF REPAIRS (CONFIRMED)				600.00

Report Ref No. CS/INC22008117/Avy3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.