



AP AUTOMOTIVE SERVICES PTE LTD
ROC / GST REG NO : 202022890H
BLOCK 9006
TAMPINES STREET 93 #01-202
SINGAPORE 528840
TEL: 6784 4465
FAX: 6787 4886

Veron.

TO: NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Vehicle No : SBR 90X

Make & Model : TOYOTA VELLFIRE 2.5Z CVT

DATE DOA : 23/07/2022

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	FRONT BUMPER	1	\$ 1,450.00	\$ X 1,450.00
2	FRONT BUMPER SIDE RETAINER	1	\$ 95.00	\$ X 95.00
3	FRONT FENDER RH	1	\$ 975.60	\$ X 975.60
4	FRONT FENDER INNER GARNISH RH	1	\$ 95.30	\$ X 95.30
5	FRONT FENDER LOWER GARNISH RH	1	\$ 87.30	\$ X 87.30
6	FRONT FENDER COWLING RH	1	\$ 249.40	\$ X 249.40
7	FRONT DOOR VIEW MIRROR COVER RH	1	\$ 988.00	\$ X 988.00
8	FRONT DOOR RH	1	\$ 1,988.90	\$ X 1,988.90
9	FRONT DOOR OUTER MOULDING RH	1	\$ 174.80	\$ X 174.80
10	FRONT DOOR REGULATOR RH	1	\$ 275.40	\$ X 275.40
11	FRONT DOOR FRAME WEATHERSTRIP RH	1	\$ 289.80	\$ X 289.80
12	FRONT DOOR LOWER GARNISH RH	1	\$ 780.90	\$ X 780.90
13	ROCKER PANEL RH	1	\$ 326.70	\$ X 326.70
14	SLIDING DOOR RH	1	\$ 1,496.50	\$ X 1,496.50
15	SLIDING DOOR PROTECTOR RH	1	\$ 1,154.30	\$ X 1,154.30
35	REAR FENDER PROTECTOR RH	1	\$ 292.70	\$ X 292.70
36	REAR BUMPER	1	\$ 590.60	\$ X 590.60
37	REAR BUMPER SIDE RETAINER	2	\$ 69.70	\$ X 139.40
			Subtotal :	\$ 11,450.60
			Less 25%	\$ 2,862.65
			Parts Total :	\$ 8,587.95

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	FRONT DOOR SEALANT RH		\$ 60.00	\$ X 60.00
2	FRONT DOOR PROTECTOR CLIPS RH (SET)		\$ 30.00	\$ X 30.00
3	FRONT DOOR INNER TRIM CLIPS RH (SET)		\$ 60.00	\$ X 60.00
4	SLIDING DOOR SEALANT RH		\$ 60.00	\$ X 60.00
5	SLIDING DOOR STEP GARNISH CLIP RH (SET)		\$ 40.00	\$ X 40.00
6	SLIDING DOOR INNER TRIM CLIP RH (SET)		\$ 60.00	\$ X 60.00
7	SLIDING DOOR STEP PANEL GARNISH CLIP RH (SET)		\$ 40.00	\$ X 40.00
8	REAR FENDER COWLING CLIP RH (SET)		\$ 60.00	\$ X 60.00
9	REAR BUMPER CLIP RH (SET)		\$ 50.00	\$ X 50.00
10	FRONT NUMBER PLATE		\$ 50.00	\$ X 50.00

LABOUR (REAR)		PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	100	\$ 2,400.00
TO SPRAY PAINT AFFECTED AREA	500	\$ 2,100.00
TO PERFORM LIGHTING & WIRING CHECK		\$ X 120.00
TO APPLY ANTI-RUST & TUFF KOTE		\$ X 250.00
TRANSFER FRONT AND REAR DOOR MECHANISM	600	\$ X 420.00
TO CHECK FOUR WHEEL ALIGNMENT		\$ X 120.00
RESET ABS LIGHT		\$ X 320.00
LABOUR TOTAL		\$ 5,730.00

Total Parts Cost	\$ 9,097.95
Total Labour Cost	\$ 5,730.00
Total Repair Cost	\$ 14,827.95

total = 600 (P/P)
02 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: