



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |  |   |            |
|--|--|---|------------|
| SOMPO INSURANCE SINGAPORE PL<br>50 RAFFLES PLACE #03-03<br>SINGAPORE LAND TOWERSINGAPORE 048623  |  | Ref: CS/SMO22008118/Uvy3q2<br>Date: 14/09/2022<br>Code: SMO |            |
| 1. Policy Particulars :- THIRD PARTY CLAIM   |  |   |            |
| Insured Veh.   | SNA 9423H  | Veh. Inspected  | SKV 2390P  |
| Policy No.   |  | Coverage (\$)   | 0.00       |
| Claim No.  | CMTD2202897/GPL  | Excess (\$)   | 0.00       |
| Assign From  | GRACE TEO  | Assign Date   | 24/08/2022 |
| 2. Vehicle Particulars & Condition   |  |   |            |
| Make & Model   | MERCEDES BENZ CLA180 (A)   | c.c   | 1595       |
| Engine No.   | HIDDEN   | Year of Reg.  | 2015       |
| Chassis No.  | WDD1173422N251755  | Colour  | MATT BLACK |
| Odometer   | 120573 KM  | Steering  | IN ORDER   |
| Brakes   | IN ORDER   | Modification  | SPORTS RIM |
| General  | GOOD   |   |            |
| 3. Conditions of Tyres   |  |   |            |
|  | Size   | Make  | Balance    |
| R/H Front Tyre   | 225/40 R18   | GOODYEAR  | 7 mm       |
| L/H Front Tyre   | 225/40 R18   | GOODYEAR  | 7 mm       |
| R/H Rear Tyre  | 225/40 R18   | GOODYEAR  | 7 mm       |
| L/H Rear Tyre  | 225/40 R18   | GOODYEAR  | 7 mm       |
| 4. Description of Damages  |  |   |            |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.<br>DAMAGES SEE DETAILS.   |  |   |            |
| 5. General Information   |  |   |            |
| Accident Date  | 11/08/2022   | Inspection Date   | 29/08/2022 |
| Survey held at   | HUP LEY HUAT MOTOR SPRAY PAINTING SVS<br>BLK 1 KAKI BUKIT AVE 6,<br>#01-35 AUTOBAY<br>SINGAPORE 417883 |   |            |
| 5a. Remarks  |  |   |            |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |   |            |
| 5b. Estimate Days of Repair  |  |   |            |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |  | 2 Working Days  |            |