

Hup Ley Huat Motor Spray Painting Services

No.1 Kaki Bukit Ave 6 #01-35 AutoBay, Singapore 417883

TEL: 6746 0674 FAX: 6841 7639

Vehicle No : SKV 2390 P

Make: Mercedes CLA

Date: 29/08/2022

Accident Date: 11/08/2022

Spare parts

QTY	List Price	Price	(S\$)
1	Rear Bumper "AMG Line"	Depcut de	1400 ✓
1	Rear Diffuser "AMG Line"	R	300 X
1	Bumper Garnish	R	100 X
1	Exhaust tip	11	300 X
1	Fender	11	1230 X

Spare Parts Subtotal

102

3330

Special Nett

Items

Qty

1	Bumper Clip	111	50 ✓
1	Rear Bumper Sensor	11	280 X
1	Number plate with casing	11	50 X

380

Labour charges

S/N

S/N		(S\$)
1	To tuff coat affected areas	11 120 X
2	To spray paint include polishing and waxing on the changed body parts, repair body portions where consistent to the accident	800 300
3	To provide labour charges, workmanship to realign body structure and damaged consistent to the accident	800 220
4	To remove and install rear sensor	120 50
5	To check and connect snap wiring	80 X

Labour charges: Subtotal

1920

ESTIMATES PARTS AND LABOR GRAND TOTAL:

5630

Not Authorised
 L/S \$1500
 2 days
 29/8/22
 HP 90296608
 Shop for other repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1400
 102
 1260
 50
 570
 1880
 20%
 1504