

not authorized
29/08/22
1/5529001
3 days
Whaphi Alwar

Our Ref.: AC2022059/TP

Vehicle number: SMU1878M

Vehicle Made & Model: VOLVO XC60

Qty	List Items	Amount \$
1	1 REAR BUMPER (TOP) <i>cut 7/10.1 2201</i>	2856.90 ✓
2	1 REAR BUMPER TOWING COVER <i>11</i>	54.20 X
3	1 REAR BUMPER (LOWER) <i>11</i>	1645.20 X
4	2 REAR BUMPER REFLECTOR @ 198.70 <i>11</i>	387.40 X
5	4 REAR BUMPER SENSOR @ 225.90 <i>11</i>	903.60 X
6	4 REAR BUMPER SENSOR HOLDER @ 42.30 <i>11</i>	169.20 X
7	1 REAR BUMPER REVERSE SENSOR WIRE HARNESS <i>11</i>	415.80 X
8	2 REAR BUMPER EXHAUST CHROME PIPE @ 385 <i>11</i>	770.00 X
9	2 REAR BUMPER EXHAUST CHROME PIPE BRACKET @ 98.70 <i>11</i>	197.40 X
10	1 REAR BUMPER REINFORCEMENT <i>11</i>	1254.90 X
11	2 REAR BUMPER SIDE RETAINER @ 125.60 <i>11</i>	251.20 X
12	1 REAR BUMPER INNER CENTER GARNISH <i>11</i>	145.80 X
13	1 REAR BUMPER UPPER CENTER GARNISH <i>11</i>	303.60 X
14	2 TAIL LAMP @ 1025.80 <i>11</i>	2051.60 X
15	2 TAIL LAMP LOWER BRACKET @ 98.70 <i>11</i>	197.40 X
16	1 TAILGATE <i>11</i>	3458.90 X
17	1 TAILGATE OUTER GARNISH <i>11</i>	897.50 X
18	1 TAILGATE EMBLEM 'XC60' <i>11</i>	132.00 X
19	1 TAILGATE EMBLEM 'T5' <i>11</i>	125.80 X
20	1 TAILGATE EMBLEM 'VOLVO' <i>11</i>	145.80 X
21	1 TAILGATE INNER LOCK <i>11</i>	485.20 X
22	1 TAILGATE LOCK CATCH <i>11</i>	45.20 X
23	1 TAILGATE WEATHER STRIP <i>11</i>	245.60 X
24	4 TAILGATE STOPPER @ 30.80 <i>11</i>	123.20 X
25	1 TAILGATE INNER TRIM (LOWER) <i>11</i>	698.50 X
26	1 REAR END PANEL <i>11</i>	2908.40 X
27	1 REAR END PANEL TOP GARNISH <i>11</i>	482.30 X
28	1 REAR FLOOR PANEL TOP BOARD <i>11</i>	1977.80 X
29	1 REAR FENDER <i>R</i>	1,987.60 X
30	1 RIM <i>0/s cut</i>	1,245.80 <i>8005/W</i>
TOTAL PRICE		26,563.80
LESS 10%		2,656.38
SUB TOTAL PRICE		23,907.42

Vehicle number: SMU1878M

Vehicle Make & Model: VOLVO XC60

Special Nett Items

1	REAR NUMBER PLATE WITH COVER	11	80.00	X
1	REAR BUMPER CLIP (SET)	111	50.00	✓
1	REAR BUMPER INNER CENTER GARNISH CLIP (SET)	11	50.00	X
1	REAR BUMPER UPPER CENTER GARNISH CLIP (SET)	11	50.00	X
2	TAIL LAMP CLIP (SET)	11	100.00	X
2	REAR FENDER INNER COWLING CLIP (SET)	11	100.00	X
1	TAILGATE WINDSCREEN SEALANT	11	80.00	X
1	REAR END PANEL SEALANT	11	200.00	X
TOTAL			710.00	

Labour charges

TO PANEL BEAT, REMOVE AND REPLACE PARTS	1800.00	400
TO SPRAY PAINT AFFECTED AREA	1800.00	400
TUFF COAT	11 200.00	X
WIRING AND BULB CHECK ON TAILAMP	11 120.00	X
REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY TO FACILIATE REPAIR	11 150.00	X
REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	180.00	50
TRANSFER TAILGATE MECHANISM	11 150.00	X
CONDUCT WATER LEAKAGE TEST	11 120.00	X
REMOVE AND RESET TAILGATE AUTO SYSTEM	11 350.00	X
REMOVE AND REFIX TAIL GATE WINDSCREEN	11 150.00	X
TOTAL	5,020.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 29,637.42

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-2201
102
P-198090
S.W-850
L-810
3680.90
2944