

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBC8843S
Accident Date : 20-Aug-2022

Our Ref : 022135 (EQ) / CHAN

LEONG SIYUN
BLK 19 JALAN TENTERAM
#26-138
Singapore 321019

No. : 06643

Date : 22-Aug-2022

PAGE : 1

ESTIMATED COST OF REPAIR FOR MIT ATTRAGE SMH5149B

1 pc Boot lid		630.00	BT
1 pc Boot lid top spoiler		440.00	cra
2 pcs Boot lid hinge	@ S\$140.00	280.00	BT
1 pc Boot lid inner lock		160.00	DP
1 pc Boot lid lock catch		20.00	X R
1 pc Boot lid rubber		110.00	DIS/OD
1 pc Boot lid cable		50.00	X SVC
1 pc Boot lid outer chrome		240.00	cra
2 pcs Boot lid license plate lamp	@ S\$ 35.00	70.00	X SVC
1 pc Boot lid "ATTRAGE" emblem		28.00	rec
1 pc Boot lid logo		30.00	rec
1 pc Boot lid "MIVEC" plate		44.00	rec
1 pc Rear windscreen glass		430.00	cut
2 pcs Rear w/s glass side moulding	@ S\$ 62.00	124.00	rec
1 pc Rear w/s glass top moulding		40.00	rec
2 pcs Rear fender	@ S\$550.00	1,100.00	Buc
2 pcs Rear fender side extension	@ S\$ 95.00	190.00	Buc
2 pcs Rear fender inner trim cover	@ S\$120.00	240.00	def
1 pc Rear n/s fender inner shield		28.00	cra
2 pcs Taillamp	@ S\$245.00	490.00	cra
2 pcs Taillamp corner panel	@ S\$ 90.00	180.00	BT
2 pcs Taillamp gasket	@ S\$ 22.00	44.00	rec
2 pcs Taillamp side clip	@ S\$ 5.00	10.00	rec
1 pc Rear end panel		370.00	BT
1 pc End panel top garnish		70.00	DIS
2 pcs End panel side guide	@ S\$ 45.00	90.00	N/S only DIS
1 pc End panel centre guide		40.00	cra
1 pc Rear bumper fascia		420.00	BT

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBC8843S

Page : 2

1 pc	Rear bumper lower spoiler		700.00	crq
2 pcs	Rear chassis extension member	@ S\$550.00	1,100.00	N/s only Bt
1 pc	Rear spare tyre panel		650.00	Bt
1 pc	Rear spare tyre board		135.00	crq
1 pc	Rear spare tyre screw & nut		80.00	Bt
1 pc	Rear exhaust pipe		440.00	Bt
1 pc	Bonnet		535.00	Buc
2 pcs	Bonnet hinge	@ S\$ 42.00	84.00	DIS
1 pc	Bonnet insulator		110.00	crq
1 pc	Bonnet inner lock		50.00	Jm
1 pc	Bonnet rubber		35.00	X SVC
1 pc	Bonnet cable		30.00	X SVC
2 pcs	Front fender	@ S\$310.00	620.00	o/s Buc
2 pcs	Front fender "ECO" emblem	@ S\$ 28.00	56.00	REC
2 pcs	Eco emblem lower chrome	@ S\$ 35.00	70.00	REC
1 pc	Front o/s fender inner shield		65.00	crq
1 pc	Front o/s fender outer garnish		20.00	DD
2 pcs	Headlamp	@ S\$410.00	820.00	o/s crq N/s mtg crq
1 pc	Front grille		340.00	crq
1 pc	Front grille logo		35.00	crq
1 pc	Front grille top cover		47.00	X SVC
8 pcs	Front grille clip	@ S\$ 2.00	16.00	REC
1 pc	Front bumper fascia		480.00	Bt
1 pc	Front bumper reinforcement		115.00	Bt
2 pcs	Front bumper side retainer	@ S\$ 12.00	24.00	DIS
1 pc	Front bumper lower grille		124.00	crq
1 pc	Frt bumper centre lower cover		70.00	X SVC
1 pc	Front bumper lower spoiler		1,300.00	crq
1 pc	Front bumper tow cover		20.00	DD
2 pcs	Front wiper garnish side	@ S\$ 20.00	40.00	X SVC
2 pcs	Horn	@ S\$ 60.00	120.00	X DD
1 pc	Radiator assy		650.00	Bt
1 pc	Radiator top guide		100.00	crq
1 pc	Radiator fan cowling		90.00	crq
1 pc	Radiator fan blade		55.00	DIS
1 pc	Radiator fan motor		285.00	Jm
1 pc	Radiator spare tank		30.00	DD
1 pc	Radiator top hose		14.00	X SVC

Con't Page 3 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBC8843S

Page : 3

1 pc Radiator lower hose
1 pc Air con condenser
2 pcs Air con condenser side guide @ S\$ 13.00
1 pc Air con suction hose
1 pc Air con discharge hose
1 pc Front top panel
1 pc Front lower support panel
1 pc Air intake air duct
1 pc Air cleaner housing assy
1 pc Engine manifold
1 pc Rear end panel air vent } supplementary
1 pc W/s glass washer tank }

20.00 / cut
520.00 / Bt / prc
26.00 / org
160.00 / Bt
170.00 / prc
135.00 / Bt
700.00 / Bt
95.00 / DD
140.00 / org
1,350.00 / DD
33.00 / DD
65.00 / DD

18,937.00
Add: 10% : 1,893.70

17846.00
1784.60
19630.60

1 pc Rear w/s glass solar film
1 pc Rear w/s glass sealant
1 pc Rear bumper reverse sensor(set)
1 pc Rear bumper clip (set)
1 pc Rear no.plate with box
1 pc Front no.plate with box
1 pc Front bumper clip (set)
1 pc Radiator coolant

20,830.70 sub.
350.00 sn
60.00 sn 40
200 300.00 sn
40.00 sn ✓
50.00 sn 45
50.00 sn 45
40.00 sn ✓
30.00 sn ✓

To towing

100.00 ✓

To rewire damaged parts and refocus
headlamp beam.

20.00 ✓

To remove & renew rear windscreen
glass and conduct water leak test.

150.00 / 20

To remove roof lining, front and
rear seats, trim board and carpet

200.00 / 20

Con't Page 4 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBC8843S

Page : 4

To apply undersealing	300.00 210
To remove and renew exhaust silencer box	80.00 60
To putty and spray replaced parts	2,400.00 2200
To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts	2,500.00 2300
Total :	<u>S\$27,500.70</u> =====

Singapore Dollars Twenty Seven Thousand Five
Hundred and Cents Seventy Only