



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC22008127/Avy3m4

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 26/09/2022

ATTN: ENG HUEY HUEY

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SDG 8389S	Veh. Inspected	SLK 3188Y
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1183616-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	23/08/2022

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ GLA180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WDC1569422J283166	Colour	SILVER
Odometer	111133 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/50 R18	CONTINENTAL	6 mm
L/H Front Tyre	235/50 R18	CONTINENTAL	6 mm
R/H Rear Tyre	235/50 R18	CONTINENTAL	6 mm
L/H Rear Tyre	235/50 R18	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION AND UNDERCARRIAGE.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/08/2022	Inspect Date / Time	23/08/2022 (11:09 AM)
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days