

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

HO LAI POH
BLK 307 TAMPINES ST 32 #06-102
SINGAPORE 520307

TP INC.
VERON

TAX INVOICE

Repair Code : CLM15621

Date in : 04/08/2022

Vehicle Num. : SLK3188Y

Model : MERCEDES BENZ GLA180 (R18 BI)

Chassis/Eng# : WDC1569422J283166/27091031038099

Contact : 96650083

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Rehnd</i>	1	1560.00	1467 1560.00 -
FRONT BUMPER LOWER LID (BLACK) <i>Cut</i>	1	368.00	368.00 ✓
FRONT BUMPER RH FOGLAMP GARNISH <i>seen</i>	1	88.00	88.00 +
FRONT BUMPER RH NOZZLE JET <i>seen</i>	1	198.00	198.00 ✓
FRONT BUMPER RH NOZZLE JET BRACKET <i>seen</i>	1	72.00	72.00 +
FRONT BUMPER RH NOZZLE JET COVER <i>seen</i>	1	69.00	69.00 +
FRONT BUMPER RH PARKING SENSOR <i>Rehnd</i>	1	195.00	195.00 ✓
FRONT BUMPER RH PARKING SENSOR 'O' RING <i>seen</i>	1	18.00	18.00 ✓
FRONT BUMPER RH PARKING SENSOR HOLDER <i>seen</i>	1	25.00	25.00 ✓
FRONT BUMPER SIDE RETAINER L/R <i>RH Rehnd</i>	2	28.00	56.00 28 ✓
FRONT RH ABS SENSOR <i>seen</i>	1	375.00	375.00 +
FRONT RH FENDER <i>Dented</i>	1	975.00	975.00 ✓
FRONT RH FENDER ARCH GARNISH <i>Cut</i>	1	268.00	268.00 ✓
FRONT RH FENDER INNER BRACKET <i>seen</i>	1	92.50	92.50 ✓
FRONT RH FENDER INNER SHIELD <i>seen</i>	1	125.00	125.00 ✓
FRONT RH HEADLAMP <i>Cut</i>	1	3332.00	3,332.00 ✓
FRONT RH KNUCKLE ARM <i>seen</i>	1	1375.00	1,375.00 102 ✓
FRONT RH KNUCKLE ARM BEARING <i>seen</i>	1	670.00	670.00 ✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

HO LAI POH
BLK 307 TAMPINES ST 32 #06-102
SINGAPORE 520307

Contact : 96650083

TAX INVOICE

Repair Code : CLM15621

Date in : 04/08/2022

Vehicle Num. : SLK3188Y

Model : MERCEDES BENZ GLA180 (R18 BI)

Chassis/Eng# : WDC1569422J283166/27091031038099

FRONT RH LOWER ARM	Bent	1	905.00	656	905.00	
FRONT RH SHOCK ABSORBER	new	1	780.00		780.00	+
FRONT RH SHOCK ABSORBER TOP MOUNTING	new	1	269.00		269.00	+
FRONT RH SPORT RIM	Col	1	970.00	10414.50	970.00	✓
FRONT RH TIE ROD END	new	1	205.00	9373.05	205.00	+
Subtotal before discount					12,990.50	
Percentage discount 10%					1,299.05	
Sub-total 1					11,691.45	
FRONT BUMPER CLIPS - SET	new	1	60.00		60.00	30
FRONT BUMPER RIVET - SET	new	1	100.00		100.00	30
FRONT RH 235/50R18 TYRE	new	1	600.00		600.00	+
FRONT RH FENDER ARCH GARNISH CLIPS - SET	new	1	40.00	120	40.00	30
FRONT RH FENDER INNER SHIELD CLIPS - SET	new	1	50.00		50.00	30
Subtotal before discount					850.00	
Percentage discount 0%					0.00	
Sub-total 2					850.00	
Parts-total					12,541.45	

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

HO LAI POH
BLK 307 TAMPINES ST 32 #06-102
SINGAPORE 520307

Contact : 96650083

TAX INVOICE

Repair Code : CLM15621

Date in : 04/08/2022

Vehicle Num. : SLK3188Y

Model : MERCEDES BENZ GLA180 (R18 BI)

Chassis/Eng# : WDC1569422J283166/27091031038099

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To reset system after repair works

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

To road test driving, check and resetting wheel alignments system.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

30 80.00

100 400.00

220 380.00

80 100.00

600 1,000.00

500 700.00

40 100.00

1570

Labour Total

2,760.00

Parts & Labour Total

15,301.45

*** This is a computer-generated document which requires no signature.***

page 3

Adnan L
H/s 23/08/22
06 Days.

total: 11063.05

L/s: 88K ✓

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: