



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Ref: CS/FCI22008129/Uqy3e2 Date: 07/09/2022 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBL 390L	Veh. Inspected	SLR 5246M
Policy No.	D-22098775MFCV/150	Coverage (\$)	0.00
Claim No.	D22002649MFCV	Excess (\$)	0.00
Assign From	AINI BINTE	Assign Date	24/08/2022
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ E250 (A)	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WDD2120472A194857	Colour	BLACK / BROWN
Odometer	114710 KM	Steering	AFFECTED
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/50 R17	GOODYEAR	6 mm
L/H Front Tyre	225/50 R17	GOODYEAR	6 mm
R/H Rear Tyre	225/50 R17	GOODYEAR	6 mm
L/H Rear Tyre	225/50 R17	GOODYEAR	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	22/08/2022	Inspection Date	24/08/2022
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	