



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2300820

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 13/02/2023
Reference CC6/CTI22008130/Uea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SKK 999E
Insured Veh. GBJ 6371M
Claim No. SNM22D205968/C02
Policy No. DMCVSNW00078442200
Accident Date 23/08/2022
Inspection Date 24/08/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22008130/Uea3q2 Date: 13/02/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBJ 6371M	Veh. Inspected	SKK 999E	
Policy No.	DMCVSNW00078442200	Coverage (\$)	0.00	
Claim No.	SNM22D205968/C02	Excess (\$)	0.00	
Assign From		Assign Date	24/08/2022	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C 180 (A)	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WDD2043312G328281	Colour	SILVER	
Odometer	74263 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	CONTINENTAL	6 mm	
L/H Front Tyre	225/45 R17	CONTINENTAL	6 mm	
R/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm	
L/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/08/2022	Inspection Date	24/08/2022	
Survey held at	T K LEE AUTOMOTIVE PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKK 999E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOT LID	DENTED / BENT	2,435.77	2,435.77
1	REAR BOOT M/B STAR	NECESSARY	89.95	69.95
3	REAR BOOT M/B STAR CLIPS @\$6.50	NOT NECESSARY	19.50	-
1	REAR BOOT EMBLEM 'C180'	NECESSARY	126.20	126.20
1	REAR BOOT EMBLEM 'TG TRONIC'	NECESSARY	126.20	126.20
1	REAR BOOT CHROME MOULDING	NOT NECESSARY	249.68	-
1	REAR BOOT INNER LOCK	TWISTED / SHORTED	573.82	573.82
1	REAR BOOT INNER TRIM	NOT NECESSARY	481.60	-
10	REAR BOOT INNER TRIM CLIPS @\$6.50	NOT NECESSARY	65.00	-
1	REAR BOOT W/STRIP	NOT NECESSARY	231.18	-
2	REAR BOOT HINGES - RH / LH @\$210.50	NOT NECESSARY	421.00	-
1	REAR BUMPER	DEFORMED / TORN	1,889.61	1,889.61
1	REAR BUMPER CHROME MOULDING - CTR	NECESSARY	181.23	181.23
2	REAR BUMPER CHROME MOULDINGS - RH / LH @ \$126.03	NECESSARY	252.06	252.06
1	REAR BUMPER TOW COVER	NOT NECESSARY	18.60	-
1	REAR BUMPER TOP BRACKET - CTR	CRACKED	181.95	181.95
2	REAR BUMPER SIDE BRACKETS - RH / LH @\$115.00	NOT NECESSARY	230.00	-
2	REAR BUMPER BOTTOM BRACKETS @\$95.50	TWISTED	191.00	191.00
2	REAR BUMPER SIDE RETAINERS - RH / LH @\$126.20	NOT NECESSARY	252.40	-
1	REAR BUMPER REINFORCEMENT	DENTED	851.94	815.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	1,586.07	-
1	REAR END PANEL GARNISH	NOT NECESSARY	216.57	-
1	REAR EXHAUST SILENCER	NOT NECESSARY	1,350.00	-
2	REAR TAILLAMPS - RH / LH @\$811.22	N/S CRACKED	1,622.44	811.22
2	REAR TAILLAMP SIDE COVER - RH / LH @\$49.95	NOT NECESSARY	99.90	-
10	REAR TAILLAMP SIDE COVER CLIPS @\$6.50	NOT NECESSARY	65.00	-
2	FRONT SEAT HEADREST - RH / LH @\$1055.00	SERVICEABLE	2,110.00	-
	LESS 10% DISCOUNT		-1,591.87	-765.40
			14,326.80	6,888.61

Report Ref No. CC6/CTI22008130/Uea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIP (SN)	NECESSARY	45.00	45.00
1	SET REAR REVERSE SENSOR - 4PCS (SN)	SHORTED	420.00	200.00
1	REAR REVERSE CAMERA (SN)	SERVICEABLE	450.00	-
1	REAR BOOT TOP SPOILER (SN)	SERVICEABLE	850.00	-
			1,765.00	245.00
	<u>LABOUR</u>			
	TO CHECK REAR ELECTRICAL WIRING.		50.00	20.00
	TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR.		120.00	60.00
	TO REMOVE AND REPLACE REVERSE CAMERA & SENSORS.		80.00	50.00
	TO TUFF KOTE.		100.00	40.00
	TO REMOVE, REFIX AND RESET SEAT HEADREST SYSTEM.		450.00	100.00
	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS.		1,200.00	600.00
	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,050.00	550.00
			3,050.00	1,420.00
GRAND TOTAL			19,141.80	8,553.61
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,800.00

Report Ref No. CC6/CTI22008130/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKK 999E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKK 999E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKK 999E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

