

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008147/ACY3Q2**Date:** 21/09/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNA00150952103

Claimant Vehicle No : SJL6822Z**Insured Vehicle No :** SLX7813G

Date of Loss: 22/08/2022

Nature of Claim: TP

Claim No: SNM22D205946/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJL6822Z**

Make & Model: HONDA VEZEL, 1.5 X CVT (A)

Engine No: L15B5554618

Reg. Date: 19/10/2018 (Man. Year: 2018)

Chassis No: RU11304611

Colour: Silver

Odometer: 67323 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,162.16	3,552.80	1,609.36	31.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	1,880.00	610.00	24.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,652.16	5,432.80	2,219.36	29.00
Approved Total (Overridden) (\$\$)		4,300.00		
(\$\$)	7,652.16	4,300.00	3,352.16	43.81
+ GST 7.00/7.00% (\$\$)	535.65	301.00	234.65	43.81
Nett Amount (\$\$)	8,187.81	4,601.00	3,586.81	43.81

INSPECTION

Date of Assignment: 24/08/2022

Date Inspected: 24/08/2022 Inspected At:

Twincar Automotive Pte Ltd (Kaki Bukit)
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT
AUTOHUB
Singapore 417921

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Sep 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL6822Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	726.70 FL	*726.70 FL
2	1		*REAR BUMPER LH REFLECTOR	Cracked	171.00 FL	*171.00 FL
3	1		*REAR BUMPER LH SIDE	Deformed	195.00 FL	*195.00 FL
4	1		*REAR BUMPER LOWER COVER	Deformed	250.00 FL	*250.00 FL
5	1		*REAR BUMPER SIDE RETAINER L/R	N/S Damaged	46.00 FL	*23.00 FL
6	1		*REAR END PANEL	Dented	415.60 FL	*415.60 FL
7	1		*REAR END PANEL ANTENNA SENSOR	Not Necessary	60.10 FL	*- FL
8	1		*REAR END PANEL BUZZLE SENSOR	Cracked	85.20 FL	*85.20 FL
9	1		*REAR LH FENDER ARCH GARNISH	Not Necessary	195.00 FL	*- FL
10	1		*REAR LH FENDER INNER TRIM GARNISH	Not Necessary	295.00 FL	*- FL
11	1		*REAR LH TAILLAMP	Not Necessary	474.60 FL	*- FL
12	1		*REAR SPONGE TRAY	Cracked	221.00 FL	*221.00 FL
13	1		*REAR SPONGE TRAY TOP COVER	Torn	430.30 FL	*305.00 FL
14	1		*REAR TAILGATE	Dented	953.30 FL	*953.30 FL
15	1		*REAR TAILGATE VEZEL EMBLEM	Necessary	56.20 FL	*56.20 FL
16	1		*REAR TAILGATE INNER TRIM GARNISH	Cracked	153.40 FL	*153.40 FL
17	1		*REAR TAILGATE LH BACK RUBBER SEAL	Not Necessary	38.50 FL	*- FL
18	1		*REAR TAILGATE LH REFLECTOR	Not Necessary	413.20 FL	*- FL
19	1		*REAR TAILGATE MECHANISM LOCK	Damaged	180.00 FL	*180.00 FL
20	2		*REAR TAILGATE RUBBER GUIDE STOPPER L/R	Not Necessary	37.00 FL	*- FL
21	2		*REAR TAILGATE WINDSCREEN INNER SEAL	Necessary	130.60 FL	*130.60 FL
22	2		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	100.00 FL	*100.00 FL
23	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
24	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
25	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*60.00 FS
26	2		*SET REAR FENDER INNER TRIM GARNISH CLIPS L/R	Not Necessary	80.00 FS	*- FS
27	1		*SET REAR LH FENDER ARCH GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
28	1		*SET REAR LH FENDER INNER SHIELD CLIPS	Not Necessary	30.00 FS	*- FS
29	1		*SET REAR LH TAILLAMP CLIPS	Not Necessary	20.00 FS	*- FS
30	1		*SET REAR TAILGATE INNER TRIM GARNISH CLIPS	Necessary	60.00 FS	*30.00 FS
31	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,287.70	4,346.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,125.54	793.20
Total Parts (\$\$)	5,162.16	3,552.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	60.00	60.00
2	TO REMOVE ,REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
3	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	120.00	60.00
4	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	700.00
5	TO PROVIDE LABOUR WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENT AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	800.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	80.00	60.00
7	TO REMOVE ,REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION	New	80.00	80.00
Gross Labour Cost (\$\$)			2,490.00	1,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >