

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

MUHAMMAD IQBAL BIN NASRON
BLK 842 JURONG WEST ST 81 #02-179
SINGAPORE 640842

TP Chin.
Celine.

TAX INVOICE

Repair Code : CLM15631

Date in : 23/08/2022

Vehicle Num. : SJL6822Z

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11304611/L15B5554618

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Del d</i>	1	726.70	✓ 726.70
REAR BUMPER LH REFLECTOR <i>could</i>	1	171.00	✓ 171.00
REAR BUMPER LH SIDE <i>Del d</i>	1	195.00	✓ 195.00
REAR BUMPER LOWER COVER <i>Del d</i>	1	250.00	✓ 250.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	23.00	23 46.00
REAR END PANEL <i>Del d</i>	1	415.60	✓ 415.60
REAR END PANEL ANTENNA SENSOR <i>new</i>	1	60.10	+ 60.10
REAR END PANEL BUZZLE SENSOR <i>could</i>	1	85.20	✓ 85.20
REAR LH FENDER ARCH GARNISH <i>new</i>	1	195.00	+ 195.00
REAR LH FENDER INNER TRIM GARNISH <i>new</i>	1	295.00	+ 295.00
REAR LH TAILLAMP <i>new</i>	1	474.60	+ 474.60
REAR SPONGE TRAY <i>could</i>	1	221.00	✓ 221.00
REAR SPONGE TRAY TOP COVER <i>torn</i>	1	430.30	305 430.30
REAR TAILGATE <i>Del d</i>	1	953.30	✓ 953.30
REAR TAILGATE 'VEZEL' EMBLEM <i>new</i>	1	56.20	✓ 56.20
REAR TAILGATE INNER TRIM GARNISH <i>could</i>	1	153.40	✓ 153.40
REAR TAILGATE LH BACK RUBBER SEAL <i>new</i>	1	38.50	+ 38.50
REAR TAILGATE LH REFLECTOR <i>new</i>	1	413.20	+ 413.20

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

MUHAMMAD IQBAL BIN NASRON
 BLK 842 JURONG WEST ST 81 #02-179
 SINGAPORE 640842

Contact : 98327439

TAX INVOICE

Repair Code : CLM15631

Date in : 23/08/2022

Vehicle Num. : SJL6822Z

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11304611/L15B5554618

REAR TAILGATE MECHANISM LOCK	<i>Damaged</i>	1	180.00	✓	180.00
REAR TAILGATE RUBBER GUIDE STOPPER L/R	<i>new</i>	2	18.50	+	37.00
REAR TAILGATE WINDSCREEN INNER SEAL	<i>3 per</i>	2	65.30	✓	130.60
REAR TAILGATE WINDSCREEN MOULDING	<i>3 per</i>	2	50.00	✓	100.00
Subtotal before discount					5,627.70
Percentage discount 20%					1,125.54
Sub-total 1					4,502.16
REAR BUMPER CLIPS - SET	<i>Mr</i>	1	50.00	<i>30</i>	50.00
REAR BUMPER REVERSE SENSOR - SET	<i>Damaged</i>	1	250.00	<i>20</i>	250.00
REAR END PANEL SEALANT	<i>per</i>	1	80.00	<i>60</i>	80.00
REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET	<i>new</i>	2	40.00	+	80.00
REAR LH FENDER ARCH GARNISH CLIPS - SET	<i>new</i>	1	30.00	+	30.00
REAR LH FENDER INNER SHIELD CLIPS - SET	<i>new</i>	1	30.00	+	30.00
REAR LH TAILLAMP CLIPS - SET	<i>new</i>	1	20.00	+	20.00
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET	<i>new</i>	1	60.00	<i>30</i>	60.00
REAR TAILGATE WINDSCREEN SEALANT	<i>new</i>	1	60.00	✓	60.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MUHAMMAD IQBAL BIN NASRON
BLK 842 JURONG WEST ST 81 #02-179
SINGAPORE 640842

Contact : 98327439

TAX INVOICE

Repair Code : CLM15631

Date in : 23/08/2022

Vehicle Num. : SJL6822Z

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11304611/L15B5554618

Subtotal before discount 660.00

Percentage discount 0% 0.00

Sub-total 2 660.00

Parts-total 5,162.16

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total 2,490.00

Parts & Labour Total 7,652.16

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
L/S 24/08/22
06 days.
Total: 543280
L/S: A.3K ✓