



TAN CHONG INDUSTRIAL MACHINERY PTE LTD
23 JALAN BUROH
SINGAPORE 619479
TEL:67038755 FAX:62665862

From ALFRED LEE Date 02-Aug-22
To EQ INSURANCE COMPANY LTD Our ref AL/8446-010/0822
Attn MOTOR CLAIM DEPT *Steve CLKK* Tel 68277880
Fax 62257402

VEH NO : XD8446P *29/8/22 1.90p m L* Model : GKB5ELDHT
Chassis : GKB4E00194 *M N y 4 Lp* Eng No : GH11716269

1. The above vehicle was inspected by TCIM and append here under is the estimated repair cost :

Claim Type: 3RD PARTY DIRECT

Description	Qty	Unit Price	discount	Amount
LH DOOR ASSY <i>DD</i>	1	\$ 6,308.80	15%	\$ 5,362.48 ✓
DOOR EMBLEM <i>AK</i>	1	\$ 178.00	15%	\$ 151.30 ✓
LH BUMPER ASSY <i>DD</i>	1	\$ 348.00	15%	\$ 295.80 ✓
LH BUMPER SIDE <i>MUS</i>	1	\$ 85.44	15%	\$ 72.62 ✓
LH SIGNAL LAMP <i>OR</i>	1	\$ 48.00	15%	\$ 40.80 ✓
LH UPPER STEP GRANISH <i>? X nn</i>	1	\$ 287.00	15%	\$ 243.95 X
LH LOWER STEP GRANISH <i>OR</i>	1	\$ 258.00	15%	\$ 219.30 ✓
LH LOWER STEEL STEP <i>OR</i>	1	\$ 245.40	15%	\$ 208.59 ✓
LH STEP HANGER BRACKET <i>OT</i>	2	\$ 274.56	15%	\$ 466.75 ✓
LH SPLASH GUARD <i>OT</i>	1	\$ 233.00	15%	\$ 198.05 ✓
LH FENDER <i>CRN</i>	1	\$ 1,033.22	15%	\$ 878.24 ✓
LOGO PAINTING <i>AK</i>	1	\$ 80.00	15%	\$ 68.00 ✓
LH MIRROR ASSY <i>OR</i>	1	\$ 195.00	15%	\$ 165.75 ✓
LH MIRROR ARM <i>OT</i>	1	\$ 486.70	15%	\$ 413.70 ✓

8541.38

Estimated parts cost \$ 8,785.33

Labour cost

To putty/primer application and spray painting including touch-up affected areas with polyurethane paint.

} \$ 450 ✓ 550.00

TO REPLACE ABOVE MENTION ITEMS.
TO STRAIGHTEN AND ALIGN BUMPER REINFORCEMENT.
CARRY OUT SIDE SLIP ALIGNMENT TEST.

} \$ 1,200 ✓ 1,920.00 (4 DAYS)

450 X 2.5

Estimated labour cost \$ 2,470.00

EST. LABOUR & PARTS COST

\$ 11,255.33

1650
supp -726.75

10,918.13

NOTE: CLAIMING FOR LOST OF USE FOR 5 DAYS. (\$200 X 5 =\$1000.00)

2. All prices quoted are subjected to 7% GST. The above quotation is based on initial visual inspection only. Please be advised that any additional parts replaced or labour performed will incur supplementary charges accordingly and a separate quote will be forwarded to you for approval.

L/S - 8734.50
= 8700

3. If you are agreeable with this quotation, kindly endorse and fax this quotation back to us in order for us to proceed with the repair.

4. Please be informed that the acceptance of this quotation will render the company herein liable for all repair costs incurred in accordance with the above quotation.

Thank you and regards



ALFRED LEE DID : 67038755
Marketing Executive HP : 97879034
Service Department
Validity of quote : 30 days from date hereof.

Authorised Signature
& CO stamp

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
Is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: XD8146P Yr Regn: 04/2/14
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: UD Trucks GBL c.o. 10837
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 531000 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: GBL 00194
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modl: NII / S/Rim / STD A/Rim or
 Tyre Size: F: 295/80R22.5
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or :

Front Rear
 R/Bal. 4 mm R/Bal. 4 mm
 L/Bal. 4 mm L/Bal. 4 mm
 D.O.A. 27/7/22 D.O.I. 29/8/22
 Survey held at Don Chong
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MY-120K Rem</u>
	<u>12/11</u>
	<u>12/11</u>

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L.B.B. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

TOTAL