



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### OPINION ON REPAIR COST FOR VEHICLE NO. E-BIKE (CC25)

Qty	Description of Parts	Condition	Recommended (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>		
1	FRONT RIM WITH TYRE AND TUBE	BENT	89.90
1	FRONT FORK	BENT	120.00
1	FRONT & REAR ZOOM HYDRAULIC BRAKE	CUT	250.00
1	FRONT & REAR ROTOR	BENT	50.00
			509.90
	<b><u>LABOUR</u></b>		
	TRANSPORTATION.		60.00
			60.00
<b>GRAND TOTAL</b>			<b>569.90</b>

<b>RECOMMENDED COST OF REPAIRS</b>	<b>569.90</b>
------------------------------------	---------------

Report Ref No. CS/SMR22008149/Gqy3m4

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.