



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile		CS3/ASM22002660/Ecy3-1	
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Ref: CS3/ASM22002660/Ecy3-1	Date: 23/03/2022 22/08/2022
		Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SHA 6792H	Veh. Inspected	FBX 8373P
Policy No.		Coverage (\$)	0.00
Claim No.	S2M03VXY	Excess (\$)	0.00
Assign From	NG Steezy HENG XIN YI (SEAH ONG)	Assign Date	22/03/2022 22/08/2022
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	14/03/2022	Inspection Date	23/03/2022
Survey held at	I-MOTORING CREDIT PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-14 SINGAPORE 159722		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			