

LBS AUTOMOTIVE APPRAISAL PTE. LTD.

Co. Reg. No. 201408536E

Block 8 Kensington Park Drive #01-07

Singapore 557323

Telephone: 62832866, 62816690 Facsimile: 62818748, 62832166

AUTOMOBILE INSPECTION REPORT

AXA Insurance Pte Ltd
C/o Seah Ong & Partners LLP
Robinson Road
P.O. Box 1094
Singapore 902144

OUR REFERENCE: LBS/AXA/TP/PS/22/03/T056

REFERENCE: PAPER RE-INSPECTION REPORT

VEHICLE NUMBER : JSD 5159 CLAIM NUMBER : 22.29517
ACCIDENT DATE : 16.05.2021

PARTICULARS OF DAMAGED VEHICLE:

MAKE : HONDA FS150FH3 MODEL : 2017
COLOUR : MULTI COLOUR V.I.N. : PMKKC27E0HB003885

INSPECTION DETAILS AND ADJUSTMENTS: KINDLY SEE SCHEDULE/S OVERLEAF

ORIGINAL QUOTATION	\$	8,200.00
REVISED QUOTATION	\$	1,850.00 *

ESTIMATED NORMAL PERIOD FOR REPAIR: 04 WORKING DAYS
IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORIZE REPAIR.

POINT OF IMPACT/S

The impact was confined to the near side broadside portion of the motorbike.

REMARKS

Sum Insured RM \$5,000.00

* The adjusted lump sum repair cost of \$1,850.00 has exceeded the Sum Insured. Thus, the lump sum repair cost is subject to your approval.

Paper re-inspection report prepared by Mr Stan See Chew Seng

LBS AUTOMOTIVE APPRAISAL PTE. LTD.

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS:

WORKSHOP:

Ah Fook Motor.Com LLP
NO. 5 SOON LEE STREET
#01-15 PIONEER POINT
SINGAPORE 627607

OUR REFERENCE: LBS/AXA/TP/PS/22/03/T056

<u>QTY</u>	<u>DESCRIPTIONS</u>	<u>CONDITION</u>	<u>ORIGINAL QUOTATION</u>	<u>REVISED QUOTATION</u>	
VEHICLE NUMBER: JSD 5159					
1	Front handle bar (set)		\$ 258.00	\$ 95.00	✓
1	Front handle bar grip with balancer (set)		\$ 65.00	\$ 30.00	✓
1	Front brake lever		\$ 75.00	\$ NN 18.00	✗
1	Front clutch lever		\$ 75.00	\$ 18.00	✓
1	Front headlamp complete assembly (set)	Serviceable	\$ 495.00	\$ NN -	✗
1	Front headlamp top cowling	Serviceable	\$ 255.00	\$ NN -	✗
1	Front side lamp (set)		\$ 395.00	\$ 195.00	✓
1	Front lh signal lamp		\$ 75.00	\$ 28.00	✓
1	Front rh signal lamp		\$ 75.00	\$ NN 28.00	✗
1	Front lh wing mirror		\$ 65.00	\$ NN 18.00	✗
1	Front rh wing mirror		\$ 65.00	\$ 18.00	✓
1	Front fender		\$ 195.00	\$ 65.00	✓
1	Front fork stem (set)	Serviceable	\$ 85.00	\$ -	
1	Front fork assembly		\$ 1,030.00	\$ 350.00	✓
1	Front fork bearing		\$ 65.00	\$ 35.00	✓
1	Front lh fairing		\$ 455.00	\$ 235.00	✓
1	Front rh fairing		\$ 455.00	\$ NN 235.00	✗
1	Front gear selector		\$ 65.00	\$ 55.00	✓
1	Front brake pedal		\$ 65.00	\$ NN 30.00	✗
1	Front lh footrest		\$ 65.00	\$ 30.00	✓
1	Front rh footrest	Serviceable	\$ 65.00	\$ -	
1	Rear taillamp	Serviceable	\$ 108.00	\$ -	
1	Rear seat bracket	Serviceable	\$ 95.00	\$ -	
1	Rear brake lamp bracket	Serviceable	\$ 220.00	\$ -	
2	Rear footrest - lh only	Rh Serviceable	\$ 125.00	\$ 35.00	✓
1	Rear exhaust muffler assembly	Serviceable	\$ 1,095.00	\$ -	
1	Rear exhaust muffler protector side cover		\$ 125.00	\$ NN 65.00	✗
1	Rear exhausts muffler end cover		\$ 125.00	\$ NN 35.00	✗
1	Rear chassis frame	Serviceable	\$ 2,600.00	\$ -	
1	Front lh side cover		\$ 115.00	\$ 75.00	✓
1	Front rh side cover	Serviceable	\$ 115.00	\$ -	
1	Front centre cowling		\$ 195.00	\$ 135.00	✓
1	Rear brake lamp	Serviceable	\$ 45.00	\$ -	
1	Rear seat cowling	Serviceable	\$ 195.00	\$ -	
1	Rear garnish	Serviceable	\$ 125.00	\$ -	
1	Rear signal lamps (set)		\$ 145.00	\$ 80.00	✓
			\$ 9,871.00	\$ 1,908.00	
Less 10%			\$ 987.10	\$ 190.80	
			\$ 8,883.90	\$ 1,717.20	

LBS AUTOMOTIVE APPRAISAL PTE. LTD.

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS:

<u>Special Nett</u>			
1	Front number plate	\$ 25.00	\$ 12.00 ✓
1	ERP IU	\$ 156.00	\$ 156.00 ✓
1	ERP IU bracket	Serviceable \$ 25.00	\$ -
1	Rear number plate	\$ 25.00	\$ 12.00 ✓
	Labour to replace accident affected area.	\$ 400.00	\$ 300.00 ✓
	To transport bike to workshop.	\$ 60.00	\$ 60.00 ✓
	To putty & spray paint affected area.	Material W/Colour \$ 400.00	\$ -
	To conduct chassis alignment.	\$ 120.00	\$ 80.00 ✓
	To check wheel alignment.	\$ 40.00	\$ -
	To check lighting & wiring.	\$ 20.00	\$ -
	To remove & install rear exhaust pipe assy.	Refer Main Labour \$ 60.00	\$ -
		<u>\$ 10,214.90</u>	<u>\$ 2,337.20</u>

The lump sum repair cost for the entire damage works out to \$1,850.00.

4 days

Please refer to the REMARKS on cover page to compare the economical repair value of this vehicle.

This paper re-inspection is conducted on a "Without Prejudice" basis.

INSTRUCTION RECEIVED:

FROM: Miss Heng Xinyi - Seah Ong & Partners LLP

On: 23.03.2022

DATE OF REPORT: 23.03.2022

LBS AUTOMOTIVE APPRAISAL PTE. LTD.



Stan See Chew Seng
Automotive Appraiser