

# LBS AUTOMOTIVE APPRAISAL PTE. LTD.

Co. Reg. No. 201408536E

Block 8 Kensington Park Drive #01-07

Singapore 557323

Telephone: 62832866, 62816690 Facsimile: 62818748, 62832166

## AUTOMOBILE INSPECTION REPORT

AXA Insurance Pte Ltd  
C/o Seah Ong & Partners LLP  
Robinson Road  
P.O. Box 1094  
Singapore 902144

OUR REFERENCE: LBS/AXA/TP/PS/22/03/T056

REFERENCE: PAPER RE-INSPECTION REPORT

VEHICLE NUMBER : JSD 5159 CLAIM NUMBER : 22.29517  
ACCIDENT DATE : 16.05.2021

### PARTICULARS OF DAMAGED VEHICLE:

MAKE : HONDA FS150FH3 MODEL : 2017  
COLOUR : MULTI COLOUR V.I.N. : PMKKC27E0HB003885

### INSPECTION DETAILS AND ADJUSTMENTS: KINDLY SEE SCHEDULE/S OVERLEAF

ORIGINAL QUOTATION	\$	8,200.00
REVISED QUOTATION	\$	1,850.00 *

ESTIMATED NORMAL PERIOD FOR REPAIR: 04 WORKING DAYS  
IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORIZE REPAIR.

### POINT OF IMPACT/S

The impact was confined to the near side broadside portion of the motorbike.

### REMARKS

Sum Insured RM \$5,000.00

\* The adjusted lump sum repair cost of \$1,850.00 has exceeded the Sum Insured. Thus, the lump sum repair cost is subject to your approval.

Paper re-inspection report prepared by Mr Stan See Chew Seng

# LBS AUTOMOTIVE APPRAISAL PTE. LTD.

## ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS:

### WORKSHOP:

Ah Fook Motor.Com LLP  
NO. 5 SOON LEE STREET  
#01-15 PIONEER POINT  
SINGAPORE 627607

OUR REFERENCE: LBS/AXA/TP/PS/22/03/T056

<u>QTY</u>	<u>DESCRIPTIONS</u>	<u>CONDITION</u>	<u>ORIGINAL QUOTATION</u>	<u>REVISED QUOTATION</u>
VEHICLE NUMBER: JSD 5159				
1	Front handle bar (set)		\$ 258.00	\$ 95.00
1	Front handle bar grip with balancer (set)		\$ 65.00	\$ 30.00
1	Front brake lever		\$ 75.00	\$ 18.00
1	Front clutch lever		\$ 75.00	\$ 18.00
1	Front headlamp complete assembly (set)	Serviceable	\$ 495.00	\$ -
1	Front headlamp top cowling	Serviceable	\$ 255.00	\$ -
1	Front side lamp (set)		\$ 395.00	\$ 195.00
1	Front lh signal lamp		\$ 75.00	\$ 28.00
1	Front rh signal lamp		\$ 75.00	\$ 28.00
1	Front lh wing mirror		\$ 65.00	\$ 18.00
1	Front rh wing mirror		\$ 65.00	\$ 18.00
1	Front fender		\$ 195.00	\$ 65.00
1	Front fork stem (set)	Serviceable	\$ 85.00	\$ -
1	Front fork assembly		\$ 1,030.00	\$ 350.00
1	Front fork bearing		\$ 65.00	\$ 35.00
1	Front lh fairing		\$ 455.00	\$ 235.00
1	Front rh fairing		\$ 455.00	\$ 235.00
1	Front gear selector		\$ 65.00	\$ 55.00
1	Front brake pedal		\$ 65.00	\$ 30.00
1	Front lh footrest		\$ 65.00	\$ 30.00
1	Front rh footrest	Serviceable	\$ 65.00	\$ -
1	Rear taillamp	Serviceable	\$ 108.00	\$ -
1	Rear seat bracket	Serviceable	\$ 95.00	\$ -
1	Rear brake lamp bracket	Serviceable	\$ 220.00	\$ -
2	Rear footrest - lh only	Rh Serviceable	\$ 125.00	\$ 35.00
1	Rear exhaust muffler assembly	Serviceable	\$ 1,095.00	\$ -
1	Rear exhaust muffler protector side cover		\$ 125.00	\$ 65.00
1	Rear exhausts muffler end cover		\$ 125.00	\$ 35.00
1	Rear chassis frame	Serviceable	\$ 2,600.00	\$ -
1	Front lh side cover		\$ 115.00	\$ 75.00
1	Front rh side cover	Serviceable	\$ 115.00	\$ -
1	Front centre cowling		\$ 195.00	\$ 135.00
1	Rear brake lamp	Serviceable	\$ 45.00	\$ -
1	Rear seat cowling	Serviceable	\$ 195.00	\$ -
1	Rear garnish	Serviceable	\$ 125.00	\$ -
1	Rear signal lamps (set)		\$ 145.00	\$ 80.00
			\$ 9,871.00	\$ 1,908.00
Less 10%			\$ 987.10	\$ 190.80
			\$ 8,883.90	\$ 1,717.20

# LBS AUTOMOTIVE APPRAISAL PTE. LTD.

## ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS:

<u>Special Nett</u>				
1	Front number plate		\$ 25.00	\$ 12.00
1	ERP IU		\$ 156.00	\$ 156.00
1	ERP IU bracket	Serviceable	\$ 25.00	\$ -
1	Rear number plate		\$ 25.00	\$ 12.00
Labour to replace accident affected area.			\$ 400.00	\$ 300.00
To transport bike to workshop.			\$ 60.00	\$ 60.00
To putty & spray paint affected area.		Material W/Colour	\$ 400.00	\$ -
To conduct chassis alignment.			\$ 120.00	\$ 80.00
To check wheel alignment.			\$ 40.00	\$ -
To check lighting & wiring.			\$ 20.00	\$ -
To remove & install rear exhaust pipe assy.		Refer Main Labour	\$ 60.00	\$ -
			<u>\$ 10,214.90</u>	<u>\$ 2,337.20</u>

The lump sum repair cost for the entire damage works out to \$1,850.00.

Please refer to the REMARKS on cover page to compare the economical repair value of this vehicle.

This paper re-inspection is conducted on a "Without Prejudice" basis.

### INSTRUCTION RECEIVED:

FROM: Miss Heng Xinyi - Seah Ong & Partners LLP

On: 23.03.2022

DATE OF REPORT: 23.03.2022

LBS AUTOMOTIVE APPRAISAL PTE. LTD.



**Stan See Chew Seng**  
*Automotive Appraiser*