



Pte Ltd

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC number : 201015366H

REPAIR PERFORMA INVOICE



Vehicle number	YP2182P
Make / Model	MITSUBISHI CANTER
Chassis number	FEB21EA20439
Accident date	23/8/22
Reference	2208-20

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT DOOR PANEL LH	2207.70 <i>bl</i>
1	FRONT DOOR TRIM BOARD LH	678.70 x
1	FRONT DOOR WEATHERSTRIP LH	466.40 ?
1	FRONT DOOR CHECKER LH	94.60 x
2	FRONT DOOR HINGE LH	356.40 <i>RY</i>
1	FRONT STEP GARNISH LH	674.30 <i>cut</i> ✓
1	FRONT CORNER PANEL LH	556.60 <i>RY</i>
1	PILLAR 'A' LH	1629.10 <i>RY</i>
1	FRONT HEADLAMP LH	551.10 ?
1	FRONT HEADLAMP CORNER COVER LH	256.30 <i>one</i>
1	FRONT SIGNAL LAMP LH	357.00 <i>one</i>
1	FRONT BUMPER	1111.00 <i>RY</i>
2	FRONT BUMPER BRACKET	215.60 x
1	FRONT BUMPER REINFORCEMENT	712.80 x
1	FRONT BUMPER SIDE COVER (BLACK)	375.10 <i>cut</i> ✓
1	FRONT GRILLE	1215.50 ?
1	FRONT GRILLE EMBLEM - LOGO	90.20 ?
		11548.40
		Less 10%
		1154.84
		10393.56
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1 SET	FRONT GRILLE CLIP	50.00 <i>20 ?</i>
1 SET	FRONT DOOR INNER TRIM CLIP	50.00 x
		Subtotal
		100.00
		Balance C/F
		10493.56
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
1	CHECK WIRING AND LIGHTNING SYSTEM	80.00 <i>30</i>
2	R&R DOOR TRIMS AND MECHANISM FOR REPAIR	200.00 <i>60</i>
3	PANEL BEATING ON AFFECTED AREAS	1600.00 <i>4 300</i>
4	SPRAY PAINTING ON AFFECTED AREAS	1600.00 <i>300</i>
5	APPLY ANTI RUST ON AFFECTED AREAS	150.00 <i>30</i>
		Subtotal
		3630.00
		Grand total
		14123.56

Tanpin 92495749
up 25/8/22 @ 220pm
L15 Resurvey after repair
tanpin @ 11hants.com
3 days - 4 days

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date: