



Pte Ltd

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC number : 201015366H

REPAIR PERFORMA INVOICE

bizSAFE
STAR

Vehicle number YP2182P
 Make / Model MITSUBISHI CANTER
 Chassis number FEB21EA20439
 Accident date 23/8/22
 Reference 2208-20

Qty Particulars Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS

- | | |
|---|---------------------------------|
| 1 | FRONT DOOR PANEL LH |
| 1 | FRONT DOOR TRIM BOARD LH |
| 1 | FRONT DOOR WEATHERSTRIP LH |
| 1 | FRONT DOOR CHECKER LH |
| 2 | FRONT DOOR HINGE LH |
| 1 | FRONT STEP GARNISH LH |
| 1 | FRONT CORNER PANEL LH |
| 1 | PILLAR 'A' LH |
| 1 | FRONT HEADLAMP LH |
| 1 | FRONT HEADLAMP CORNER COVER LH |
| 1 | FRONT SIGNAL LAMP LH |
| 1 | FRONT BUMPER |
| 2 | FRONT BUMPER BRACKET |
| 1 | FRONT BUMPER REINFORCEMENT |
| 1 | FRONT BUMPER SIDE COVER (BLACK) |
| 1 | FRONT GRILLE |
| 1 | FRONT GRILLE EMBLEM - LOGO |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2207.70 ~~1800~~
 678.70 x un
 466.40 ~~un~~
 94.60 x un
 356.40 ~~un~~
 674.30 ~~cut~~ ~~622~~
 556.60 ~~un~~
 1629.10 ~~un~~
 551.10 ~~un~~
 256.30 ~~un~~ 222
 357.00 ~~un~~ 256
 1111.00 ~~un~~
 215.60 x un
 712.80 x un.
 375.10 ~~cut~~ 334
 1215.50 ~~un~~ 952
 90.20 ~~un~~

Less 10%

11548.40
 1154.84
 10393.56
 4827.30
 4344.57

PARTS REPLACEMENT - SPECIAL NETT ITEMS

- | | |
|-------|----------------------------|
| 1 SET | FRONT GRILLE CLIP |
| 1 SET | FRONT DOOR INNER TRIM CLIP |

50.00 20 ~~un~~
 50.00 x un

Subtotal

100.00

Balance C/F

10493.56

LABOUR AND MISCELLANEOUS CHARGES

- | | |
|---|---|
| 1 | CHECK WIRING AND LIGHTNING SYSTEM |
| 2 | R&R DOOR TRIMS AND MECHANISM FOR REPAIR |
| 3 | PANEL BEATING ON AFFECTED AREAS |
| 4 | SPRAY PAINTING ON AFFECTED AREAS |
| 5 | APPLY ANTI RUST ON AFFECTED AREAS |

80.00 30
 200.00 60
 1600.00 300
 1600.00 300 220
 150.00 30.

- Subtotal

3630.00

Grand total

14123.56

Tanpin 92495749
 up 25/8/22 @ 220pm
 L/S Resurvey after repair
 Tanpin @ 14hant.com
 3 days - 3 days

4344.57
 20
 720
 5084.57
 L/\$4050
 4 DAYS

all days