

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0719/2022/EQ
DATE : 20-Aug-22
WIP : 38156

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 24/8/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

6 days exclude 1 Sunday

Johnny Boo 1 Nov 22

OWNER'S NAME : MR. LOO HUAN LIONG
ADDRESS : BLK 431A BEDOK NORTH ROAD
#06-441
SINGAPORE 461431
TELEPHONE : HP +65 86606778
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900233479-01
VEHICLE NO : **SMQ 241 C**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI S-TRONIC
MODEL YEAR : 25/10/2019
ENGINE NO : CHZ C34871
CHASSIS NO : WAUZZZ8V9LA007106
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Aug-22
PLACE OF ACCIDENT : BEDOK NORTH ROAD JUNCTION

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMQ 241 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS	
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00		
2	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR 'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	800.00	\$	280.00
3	TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW RHS FRONT FENDER AND RHS FRONT DOOR AND RHS REAR DOOR. TO REPAIR RHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,500.00	\$	500.00
4	TO RESPRAY RHS FRONT FENDER, RHS FRONT DOOR, RHS REAR DOOR, RHS SILL PANEL AND RHS WING MIRROR COVER.	\$	4,500.00	\$	2,200.00
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 10,352.00	\$	3,172.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 241 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT FENDER - RH	1	\$ 954.00	
2	FRONT DOOR - RH	1	\$ 3,265.00	\$ 2,612.00
3	FRONT OUTER DOOR SEAL - RH	1	\$ 179.00	\$ 142.80
4	BONDING AGENT	1	\$ 51.00	
5	CLEANING SOLUTION	1	\$ 74.00	
6	APPLICATOR	1	\$ 9.00	
7	FRONT DOOR ATTACHMENT PARTS	1	\$ 252.00	
8	FRONT DOOR CATCH - RH	1	\$ 116.00	
9	FRONT TYRE PRESSURE DATA PLATE	1	\$ 34.00	\$ 26.96
10	FRONT WINDOW SLOT SEALTRIM STRIP - RH	1	\$ 346.00	
11	REAR DOOR - RH	1	\$ 3,265.00	
12	REAR OUTER DOOR SEAL - RH	1	\$ 179.00	
13	BONDING AGENT	1	\$ 51.00	
14	CLEANING SOLUTION	1	\$ 74.00	
15	APPLICATOR	1	\$ 9.00	
16	REAR DOOR CATCH - RH	1	\$ 105.00	
17	REAR WINDOW SLOT SEAL TRIM STRIP- RH	1	\$ 331.00	
18	STONE CHIP	S/N	\$ 180.00	
19	SUNDRIES		\$ 400.00	\$ 24.56
TOTAL SPARE PARTS			\$ 9,874.00	\$ 2,806.32
TOTAL LABOUR CHARGES			\$ 10,352.00	\$ 3,172.00
GRAND TOTAL			\$ 20,226.00	\$ 5,978.32

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-05/10/22



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT