

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	19 Aug 2022 19:37	Clm Veh Model Changed		[] Merimen Administrator
2	19 Aug 2022 19:37	Clm Created	Reg No: SNF3497H. Policy No: 7220054902. Acct Date: 2022/08/08. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SP14228J0005	[I] Merimen Administrator
3	25 Aug 2022 10:25	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] CELINE FONG
4	25 Aug 2022 10:25	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CELINE FONG
5	25 Aug 2022 10:25	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CELINE FONG
6	25 Aug 2022 10:25	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/09/05	[A] CELINE FONG
7	25 Aug 2022 10:25	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] CELINE FONG
8	25 Aug 2022 10:25	Clm Registration Modified	Rep:1137->200611.	[A] CELINE FONG
9	25 Aug 2022 10:25	Clm Veh Model Changed	(207164) AUDI A3 1.5 SEDAN TFSI S TRONIC (18") (A).	[A] CELINE FONG
10	25 Aug 2022 10:26	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CELINE FONG
11	25 Aug 2022 16:53	Clm Registration Modified	Init.Est.:->5,000 - 6,000. Excess: -> 800.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Hor, Yinrul
12	26 Aug 2022 12:11	Adj Rpt Initiated		[A] Renee
13	26 Aug 2022 12:11	Clm Dtl Modified	Claim Conclusion: -> 3.	[A] Renee
14	26 Aug 2022 12:11	Clm Dtl Modified	JPJ Reg. Date: -> 2022/05/23.	[A] Renee
15	26 Aug 2022 12:11	Clm Details Notified		[A] Renee
16	26 Aug 2022 16:09	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/09/05	[A] SHIAU CHAN

AUDIT TRAIL				
No.	On	Audit	Remarks	By
17	26 Aug 2022 16:10	Adj Mandate Request	Cur.Req:5769.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NO T AUTHORISE REPAIR.	[A] SHIAU CHAN
18	26 Aug 2022 21:10	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/09/05. Mandate Remarks: Vehicle may commence repair Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after re	[I] Lim, Kok-Chong
19	26 Aug 2022 21:10	Adj Mandate Set	Approved:4824.00:Vehicle may commence repair Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for a ll NEW Panels and Parts required after repair and document into Merimen.	[I] Lim, Kok-Chong

Date
From



Date
To



Audit
Type

None



Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History								
Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2834971	26 Aug 2022 12:11:44	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SNF3497H		11.00