

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0720/2022/EQ
DATE : 20-Aug-22
WIP : 38211

Xiao Chun.

03 Days.

\$4478.80.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 24/8/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. KON WEI SHENG
ADDRESS : BLK 485B CHOA CHU KANG AVE 5
#15-114
SINGAPORE 682485
TELEPHONE : HP +65 98321401
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220054902
VEHICLE NO : **SNF 3497 H**
MODEL CODE : AUDI A3 SB 1.5 TFSI
MODEL YEAR : 23/5/2022
ENGINE NO : DFY 308671
CHASSIS NO : WAUZZZGY1NA027039
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8-Aug-22
PLACE OF ACCIDENT : EXIT 8B SLIP ROAD, FROM
BKE TO MANDAI AVENUE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLATMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNF 3497 H

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N S	480.00	✓✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N S	800.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	S	1,200.00	500 ✓
4	TO RESPRAY FRONT BUMPER.	S	1,200.00	550 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N S	292.00	192 ✓
TOTAL LABOUR CHARGES		:	<u>\$ 3,972.00</u>	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 3497 H

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Rebored</i>	1	\$ 1,677.00	✓	1341.60
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 290.00	+	
3	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>new</i>	2	\$ 260.00	+	
4	FRONT BUMPER GRILLE - LOWER CENTRE <i>cracked</i>	1	\$ 433.00	✓	346.00
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	1	\$ 265.00	?	X
6	FRONT BUMPER AIR GUIDE - LH / RH <i>new</i>	2	\$ 134.00	+	
7	FRONT BUMPER SPOILER <i>new</i>	1	\$ 326.00	+	
8	FRONT BUMPER TRIM COVER - LH / RH	2	\$ 208.00	+	
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 342.00	+	
10	FRONT BUMPER SENSOR SUPPORT - LH / RH	2	\$ 86.00	+	
11	RADIATOR GRILLE <i>cracked</i>	1	\$ 932.00	✓	745.60
12	RADIATOR GRILLE CLOSING ELEMENT - CENTER <i>cracked</i>	1	\$ 210.00	?	168.00 ✓
13	FRONT BUMPER FOAM FILLER PIECE <i>cracked</i>	1	\$ 120.00	?	95.60 ✓
14	FRONT BUMPER CARRIER <i>new</i>	1	\$ 748.00	+	
15	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$ 108.00	+	
16	RADIATOR SUPPORT BRACKET <i>new</i>	1	\$ 93.00	+	
17	CAUTION SIGN STICKER	1	\$ 16.00	+	
18	AIR CONDITIONER STICKER	1	\$ 9.00	+	
19	HORN SIGNAL LOW TONE - LH <i>NOT</i>	1	\$ 154.00	+	
20	HORN SIGNAL HIGH TONE - RH <i>new</i>	1	\$ 162.00	+	
SUB TOTAL SPARE PARTS			\$ 6,573.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 3497 H

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	HORN BRACKET <i>Not in</i>	4	\$ 107.00	+	
22	HORN BRACKET UPPER - LH / RH <i>Not in</i>	2	\$ 70.00	+	
23	FRONT PARKING AID SENSOR - INNER / OUTER <i>Not in</i>	2	\$ 558.00	+	
24	FRONT PARKING AID SEAL RING <i>Not in</i>	4	\$ 52.00	+	
25	HEADLIGHT - LH / RH <i>Not in</i>	2	\$ 8,168.00	+	
26	HEADLIGHT LIFT CYLINDER - LH / RH <i>Not in</i>	2	\$ 422.00	+	
27	HEADLIGHT HOSE <i>Not in</i>	1	\$ 108.00	+	
28	RADIATOR AIR GUIDE SEAL - RH <i>Not in</i>	1	\$ 14.00	+	
29	FRONT AIR GUIDE - LH / RH <i>Not in</i>	2	\$ 84.00	+	
30	OUTSIDE TEMPERATURE SENSOR HOLDER <i>Not in</i>	1	\$ 6.00	+	
31	FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	✓	✓
32	SUNDRIES <i>Not in</i>		\$ 350.00	×	×
TOTAL SPARE PARTS		:	\$ 16,572.00		
TOTAL LABOUR CHARGES		:	\$ 3,972.00		
GRAND TOTAL		:	\$ 20,544.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*
SURVEYED DATE : *24/08/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *NH Authorised, 03 Days. H.S.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT