

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22008158/RQCE2**Date:** 01/12/2022**REFERENCE**

Insured/Claimant:	LAM PEK YING	Policy No:	2100468761	
Date of Loss:	22/08/2022	Nature of Claim:	OD	Claim No: 7176996611SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC8775L		
Make & Model:	AUDI A3, 1.4 SEDAN TFSI (ATTRACTION) (A)	Engine No:	CZC540605
Reg. Date:	27/05/2016 (Man. Year: 2016)	Chassis No:	WAUZZZ8V5G1089776
Colour:	Grey	Odometer:	160356 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$68,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	35,768.00	12,117.60	23,650.40	66.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,664.00	7,994.00	9,670.00	54.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	53,432.00	20,111.60	33,320.40	62.36
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	52,932.00	19,611.60	33,320.40	62.95
+ GST 7.00/7.00% (S\$)	3,705.24	1,372.81	2,332.43	62.95
Nett Amount (S\$)	56,637.24	20,984.41	35,652.83	62.95

INSPECTION

Date of Assignment:	25/08/2022	
Date Inspected:	24/08/2022	Inspected At: 24 Benoi Sector Singapore 629857 Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,377.00 FS	*1,901.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	195.00 FS	*- FS
3	1		*FRONT BUMPER TRIM - RH	Serviceable	182.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Serviceable	175.00 FS	*- FS
5	4		*FRONT BUMPER PULL STRAP - LOWER	Not Necessary	231.00 FS	*- FS
6	1		*FRONT BUMPER GUIDE SECTION - RH	Cracked	43.00 FS	*34.24 FS
7	1		*FRONT AIR GUIDE GRILLE - RH	Missing	122.00 FS	*97.20 FS
8	1		*RADIATOR GRILLE	Cracked	765.00 FS	*612.00 FS
9	1		*RADIATOR GRILLE COVER	Serviceable	109.00 FS	*- FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Serviceable	154.00 FS	*- FS
11	1		*FRONT REINFORCEMENT BEAM COVER	Serviceable	63.00 FS	*- FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM	Serviceable	847.00 FS	*- FS
13	1		*HORN SIGNAL HIGH TONE - RH	Bent	213.00 FS	*170.00 FS
14	1		*FRONT FENDER - RH	Buckled	954.00 FS	*763.20 FS
15	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	75.00 FS	*- FS
16	1		*FRONT FENDER BRACKET	Necessary	46.00 FS	*36.40 FS
17	1		*FRONT FENDER RIVET (6PCS)	Necessary	23.00 FS	*18.24 FS
18	1		*FRONT FENDER BRACE	Bent	107.00 FS	*85.60 FS
19	1		*FRONT FENDER BRACKET - RH	Necessary	31.00 FS	*24.24 FS
20	1		*FRONT WHEEL HOUSING LINER - RH	Deformed	183.00 FS	*146.40 FS
21	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS - RH	Not Necessary	93.00 FS	-
22	1		*BONNET	Repair	3,348.00 FS	*- FS
23	1		*BONNET STRIKER	Not Necessary	123.00 FS	*- FS
24	1		*BONNET EDGE PROTECTION	Not Necessary	31.00 FS	*- FS
25	1		*BONNET LOCK	Not Necessary	228.00 FS	*- FS
26	1		*BONNET CATCH HOOK	Not Necessary	71.00 FS	*- FS
27	1		*HEADLIGHT - RH	Cracked	2,810.00 FS	*2,248.00 FS
28	1		*HEADLIGHT BULB - RH	Serviceable	454.00 FS	*- FS
29	1		*HEADLIGHT POWER MODULE - RH	Not Necessary	635.00 FS	*- FS
30	1		*HEADLIGHT CONTROL UNIT - RH	Not Necessary	1,279.00 FS	*- FS
31	1		*HEADLIGHT HOSE - RH	Not Necessary	60.00 FS	*- FS
32	1		*HEADLIGHT LIFT CYLINDER - RH	Not Necessary	211.00 FS	*- FS
33	1		*LIFT CYLINDER HOSE	Not Necessary	204.00 FS	*- FS
34	1		*LOCK CARRIER	Not Necessary	806.00 FS	*- FS
35	6		*RADIATOR COOLANT	Not Necessary	297.00 FS	*- FS
36	1		*RADIATOR AIR GUIDE - RH	Not Necessary	28.00 FS	*- FS
37	1		*RADIATOR OUTER SEAL STRIP - RH	Not Necessary	9.00 FS	*- FS
38	1		*RADIATOR AIR GUIDE - UPPER CENTRE	Not Necessary	14.00 FS	*- FS
39	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
40	1		*FRONT DOOR - RH	Bent	3,265.00 FS	*2,612.00 FS
41	1		*FRONT OUTER DOOR SEAL - RH	Necessary	179.00 FS	*142.80 FS
42	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
43	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
44	1		*APPLICATOR	Not Necessary	9.00 FS	*- FS
45	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	252.00 FS	*- FS
46	1		*FRONT DOOR CATCH - RH	Not Necessary	116.00 FS	*- FS
47	1		*FRONT TYRE PRESSURE DATA PLATE	Necessary	34.00 FS	*26.96 FS
48	1		*FRONT WINDOW SLOT SEAL TRIM STRIP - RH	Not Necessary	346.00 FS	*- FS
49	1		*FRONT WINDOW GUIDE TRIM STRIP - RH	Not Necessary	287.00 FS	*- FS
50	1		*FRONT WATER DEFLECTOR STRIP - RH	Not Necessary	104.00 FS	*- FS
51	1		*FRONT ALUMINIUM RIM - RH	Scratched	1,303.00 FS	*1,042.40 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*FRONT ASSEMBLY CARRIER	Not Necessary	1,108.00 FS	*- FS
53	1		*FRONT BONDED RUBBER BUSHES - UPPER / LOWER	Not Necessary	179.00 FS	*- FS
54	1		*FRONT LOWER CONTROL ARM - RH	Bent	394.00 FS	*314.80 FS
55	1		*FRONT STABILIZER - RH	Serviceable	452.00 FS	*- FS
56	1		*FRONT WHEEL BEARING HOUSING - RH	Bent	628.00 FS	*502.40 FS
57	1		*FRONT WHEELHUB BEARING - RH	Bent	554.00 FS	*443.20 FS
58	1		*FRONT LOWER BALL JOINT - RH	Bent	137.00 FS	*109.60 FS
59	1		*FRONT COUPLING ROD - RH	Serviceable	105.00 FS	*- FS
60	1		*FRONT GAS SHOCK ABSORBER - RH	Bent	282.00 FS	*225.60 FS
61	1		*FRONT DRIVE SHAFT - RH	Serviceable	1,521.00 FS	*- FS
62	1		*FRONT STEERING RACK	Serviceable	5,552.00 FS	*- FS
63	1		*SET FRONT STEERING BOX REPAIR	Necessary	50.00 FS	*40.00 FS
64	1		*FRONT INNER TIE ROD - RH	Bent	99.00 FS	*78.56 FS
65	1		*FRONT OUTER TIE ROD END - RH	Bent	126.00 FS	*100.40 FS
66	1		*FRONT NO PLATE	Not Necessary	60.00 FS	-
67	1		*RHS FRONT TYRE	Not Necessary	0.00 FS	*- FS
68	1		*SUNDRIES	Necessary	700.00 FS	*225.52 FS
69	1		*AIR GUIDE GRILLE - LH (Supplementary)	Cracked	122.00 FS	*97.20 FS
70	1		*FRONT FENDER CLOSING ELEMENT - RH (Supplementary)	Not Necessary	37.00 FS	*- FS
71	1		*SIGN CAUTION STICKER (Supplementary)	Necessary	16.00 FS	*12.40 FS
72	1		*STICKER AIR CONDITIONER (Supplementary)	Necessary	9.00 FS	*6.64 FS
F=Franchise part. S=SpcNett.				Total Parts (S\$)	35,768.00	12,117.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS FOR R1234	New	1,500.00	0.00
4	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	400.00	280.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET, RHS FRONT DOOR AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,400.00	1,500.00
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, RHS UPPER A-PILLAR AND RHS FRONT DOOR	New	5,000.00	2,200.00
7	TO RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME	New	2,500.00	2,500.00
8	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	620.00	520.00
9	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	484.00	384.00
Gross Labour Cost (\$\$)			17,664.00	7,994.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >