

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0723/2022/EQ
DATE : 23-Aug-22
WIP : 38490

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/08/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Rasul

8 days exclude 1 Sunday

Johnny Boo 15 Nov 22

OWNER'S NAME : MS LAM PEK YING
ADDRESS : 3 PASIR RIS VIEW
SINGAPORE 518586

TELEPHONE : HP +65 91899940
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100468761-06
VEHICLE NO : **SLC 8775 L**
MODEL CODE : A3 SEDAN 1.4 TFSI
MODEL YEAR : 27/5/2016
ENGINE NO : CZC 540605
CHASSIS NO : WAUZZZ8V5G1089776
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 22-Aug-22
PLACE OF ACCIDENT : MOHAMED SULTAN ROAD IN FRONT
OF SULTAN LINK BLDG

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLC 8775 L

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	\$	360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	\$	250.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$	1,500.00		
4	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	400.00	\$	280.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET, RHS FRONT DOOR AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	6,400.00	\$	1,500.00
TOTAL LABOUR CHARGES		:	\$	9,060.00	\$ 2,390.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLC 8775 L

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 2,390.00
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, RHS UPPER A-PILLAR AND RHS FRONT DOOR.	\$	5,000.00	\$ 2,200.00
7	TO RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$	2,500.00	\$ 2,500.00
8	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	620.00	\$ 520.00
9	TO CARRY OUT PRE/POST DISGNOSTIC CHECK.	S/N \$	484.00	\$ 384.00
TOTAL LABOUR CHARGES		:	\$ 17,664.00	\$ 7,994.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLC 8775 L

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,377.00	\$	1,901.60
2	FRONT BUMPER FIXING PARTS	1	\$ 195.00		
3	FRONT BUMPER TRIM - RH	1	\$ 182.00		
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 175.00		
5	FRONT BUMPER PULL STRAP - LOWER	4	\$ 231.00		
6	FRONT BUMPER GUIDE SECTION - RH	1	\$ 43.00	\$	34.24
7	FRONT AIR GUIDE GRILLE - RH	1	\$ 122.00	\$	97.20
8	RADIATOR GRILLE	1	\$ 765.00	\$	612.00
9	RADIATOR GRILLE COVER	1	\$ 109.00		
10	FRONT BUMPER FOAM FILLER PIECE	1	\$ 154.00		
11	FRONT REINFORCEMENT BEAM COVER	1	\$ 63.00		
12	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 847.00		
13	HORN SIGNAL HIGH TONE - RH	1	\$ 213.00	\$	170.00
14	FRONT FENDER - RH	1	\$ 954.00	\$	763.20
15	FRONT FENDER ATTACHMENT PARTS	1	\$ 75.00		
16	FRONT FENDER BRACKET	1	\$ 46.00	\$	36.40
17	FRONT FENDER RIVET	6	\$ 23.00	\$	18.24
18	FRONT FENDER BRACE	1	\$ 107.00	\$	85.60
19	FRONT FENDER BRACKET - RH	1	\$ 31.00	\$	24.24
20	FRONT WHEEL HOUSING LINER - RH	1	\$ 183.00	\$	146.40
SUB TOTAL SPARE PARTS		:	\$ 6,895.00	\$	3,889.12

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLC 8775 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 3,889.12</i>
21	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS - RH	1	\$ 93.00	
22	BONNET	1	\$ 3,348.00	
23	BONNET STRIKER	1	\$ 123.00	
24	BONNET EDGE PROTECTION	1	\$ 31.00	
25	BONNET LOCK	1	\$ 228.00	
26	BONNET CATCH HOOK	1	\$ 71.00	
27	HEADLIGHT - RH	1	\$ 2,810.00	<i>\$ 2,248.00</i>
28	HEADLIGHT BULB - RH	1	\$ 454.00	
29	HEADLIGHT POWER MODULE - RH	1	\$ 635.00	
30	HEADLIGHT CONTROL UNIT - RH	1	\$ 1,279.00	
31	HEADLIGHT HOSE - RH	1	\$ 60.00	
32	HEADLIGHT LIFT CYLINDER - RH	1	\$ 211.00	
33	LIFT CYLINDER HOSE	1	\$ 204.00	
34	LOCK CARRIER	1	\$ 806.00	
35	RADIATOR COOLANT	6	\$ 297.00	
36	RADIATOR AIR GUIDE - RH	1	\$ 28.00	
37	RADIATOR OUTER SEAL STRIP - RH	1	\$ 9.00	
38	RADIATOR AIR GUIDE - UPPER CENTRE	1	\$ 14.00	
39	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00	
40	FRONT DOOR - RH	1	\$ 3,265.00	<i>\$ 2,612.00</i>
SUB TOTAL SPARE PARTS		:	\$ 13,987.00	<i>\$ 8,749.12</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLC 8775 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 8,749.12
41	FRONT OUTER DOOR SEAL - RH	1	\$ 179.00	\$ 142.80
42	BONDING AGENT	1	\$ 51.00	
43	CLEANING SOLUTION	1	\$ 74.00	
44	APPLICATOR	1	\$ 9.00	
45	FRONT DOOR ATTACHMENT PARTS	1	\$ 252.00	
46	FRONT DOOR CATCH - RH	1	\$ 116.00	
47	FRONT TYRE PRESSURE DATA PLATE	1	\$ 34.00	\$ 26.96
48	FRONT WINDOW SLOT SEAL TRIM STRIP - RH	1	\$ 346.00	
49	FRONT WINDOW GUIDE TRIM STRIP - RH	1	\$ 287.00	
50	FRONT WATER DEFLECTOR STRIP - RH	1	\$ 104.00	
51	FRONT ALUMINIUM RIM - RH	1	\$ 1,303.00	\$ 1,042.40
52	FRONT ASSEMBLY CARRIER	1	\$ 1,108.00	
53	FRONT BONDED RUBBER BUSHES - UPPER / LOWER	1	\$ 179.00	
54	FRONT LOWER CONTROL ARM - RH	1	\$ 394.00	\$ 314.80
55	FRONT STABILIZER - RH	1	\$ 452.00	
56	FRONT WHEEL BEARING HOUSING - RH	1	\$ 628.00	\$ 502.40
57	FRONT WHEELHUB BEARING - RH	1	\$ 554.00	\$ 443.20
58	FRONT LOWER BALL JOINT - RH	1	\$ 137.00	\$ 109.60
59	FRONT COUPLING ROD - RH	1	\$ 105.00	
60	FRONT GAS SHOCK ABSORBER - RH	1	\$ 282.00	\$ 225.60
SUB TOTAL SPARE PARTS			\$ 6,594.00	\$ 11,556.88

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLC 8775 L

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	11,556.88
61	FRONT DRIVE SHAFT - RH	1	\$ 1,521.00		
62	FRONT STEERING RACK	1	\$ 5,552.00		
63	FRONT STEERING BOX REPAIR SET	1	\$ 50.00	\$	40.00
64	FRONT INNER TIE ROD - RH	1	\$ 99.00	\$	78.56
65	FRONT OUTER TIE ROD END - RH	1	\$ 126.00	\$	100.40
66	FRONT NO PLATE	S/N	\$ 60.00		
67	RHS FRONT TYRE	S/N	TBC		
68	SUPPLEMENTARY		\$ 184.00	\$	116.24
69	SUNDRIES		\$ 700.00	\$	225.52
TOTAL SPARE PARTS			:	\$ 35,768.00	\$ 12,117.60
TOTAL LABOUR CHARGES			:	\$ 17,664.00	\$ 7,994.00
GRAND TOTAL			:	\$ 53,432.00	\$ 20,111.60

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bi-05/10/22

Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0723/2022/EQ 5-Sep-22 CHANG 1 of 1 SLC 8775 L AUDI A3 SEDAN 1.4 TFSI	
Quantity	Description		Unit Price	Amount
<u>Parts</u>				
1	AIR GUIDE GRILLE - LH	1	\$ 122.00	\$ 97.20
2	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 37.00	
3	SIGN ' CAUTION ' STICKER	1	\$ 16.00	\$ 12.40
4	STICKER AIR CONDITIONER	1	\$ 9.00	\$ 6.64
	GRAND TOTAL		\$ 184.00	\$ 116.24

For Premium Automobiles Pte Ltd

Authorized Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT