

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFS 2221 U

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>de</i>	1	\$	2,377.00	1901.60 ✓
2	FRONT BUMPER FIXING PARTS ? <i>nn</i>	1	\$	195.00	
3	FRONT BUMPER TRIM COVER - RH <i>de</i>	1	\$	182.00	145.20 ✓
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE ? <i>nn</i>	1	\$	175.00	
5	FRONT BUMPER PULL STRAP LOWER <i>ca</i>	<i>13</i>	\$	231.00	138.48 ✓
6	FRONT BUMPER GUIDE SECTION - RH ? <i>nn</i>	1	\$	43.00	
7	RADIATOR AIR GUIDE GRILLE - RH <i>ms</i>	1	\$	122.00	97.20 ✓
8	RADIATOR GRILLE <i>ca</i>	1	\$	765.00	612.00 ✓
9	RADIATOR GRILLE COVER ? <i>work</i>	1	\$	109.00	87.20 ✓
10	FRONT BUMPER REINFORCEMENT BEAM ? <i>nn</i>	1	\$	847.00	
11	FRONT BUMPER FOAM FILLER PIECE ? <i>turn</i>	1	\$	154.00	122.80 ✓
12	FRONT BUMPER REINFORCEMENT BEAM COVER ? <i>destroyed</i>		\$	63.00	49.84 ✓
13	HORN SIGNAL HIGH TONE- RH ? <i>nn</i>	1	\$	213.00	
14	FRONT FENDER - RH <i>54</i>	1	\$	954.00	763.20 ✓
15	FRONT FENDER ATTACHMENT PARTS ? <i>nn</i>	1	\$	75.00	
16	FRONT FENDER BRACET <i>rec</i>	1	\$	46.00	36.40 ✓
17	FRONT FENDER RIVET <i>m</i>	6	\$	23.00	18.24 ✓
18	FRONT FENDER BRACE ? <i>Brace</i>	1	\$	107.00	85.60 ✓
19	FRONT FENDER BRACKET - RH ? <i>55</i>	1	\$	31.00	24.24 ✓
20	FRONT WHEEL HOUSING LINER - RH <i>X nn</i>	1	\$	183.00	
SUB TOTAL SPARE PARTS			:	\$	6,895.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFS 2221 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS X nn	1	\$ 93.00	
22	BONNET bue ✓	1	\$ 3,348.00	2678.40 ✓
23	BONNET ATTACHMENT PARTS ? nn	1	\$ 172.00	
24	BONNET HINGE - LH / RH bt ✓	2	\$ 136.00	108.48 ✓
25	FRONT BONNET EDGE PROTECTION pe ✓	1	\$ 31.00	24.72 ✓
26	BONNET GAS FILLED STRUT ? Don	1	\$ 110.00	88 ✓
27	BONNET STRIKER ? nn	1	\$ 123.00	
28	BONNET LOCK bt ✓	1	\$ 228.00	182.00 ✓
29	BONNET CATCH HOOK ? sr	1	\$ 71.00	56.32 ✓
30	BONNET CATCH HOOK ? sr	1	\$ 100.00	nn
31	BONNET BOWDEN CABLE ? nn	1	\$ 64.00	
32	BONNET RELEASE CABLE COVER ? nn	1	\$ 11.00	
33	HEADLIGHT - RH bro ✓	1	\$ 2,810.00	2248.00 ✓
34	HEADLIGHT POWER MODULE ? Don	1	\$ 635.00	507.60 ✓
35	GAS DISCHARGE LAMP ? Don	1	\$ 454.00	nn
36	HEADLIGHT CONTROL UNIT ? dm dm	1	\$ 1,279.00	1023.20 ✓
37	HEADLIGHT HOSE - RH ? nn	1	\$ 60.00	
38	LIFT CYLINDER - RH ? nn	1	\$ 211.00	
39	LIFT CYLINDER HOSE ? nn	1	\$ 204.00	
40	LOCK CARRIER ca ✓	1	\$ 806.00	644.80 ✓

SUB TOTAL SPARE PARTS

: \$ 10,946.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NDRA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFS 2221 U

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	OUTSIDE TEMPERATURE SENSOR BRACKET ? <i>Don</i>	1	\$ 21.00	16.32 ✓
42	READY-MIX COOLANT <i>re</i> ✓	6	\$ 297.00	237.12 ✓
43	RADIATOR AIR GUIDE - RH ? <i>defunct</i>	1	\$ 28.00	22.16 ✓
44	RADIATOR AIR GUIDE OUTER SEAL - RH ? <i>nn</i>	1	\$ 9.00	
45	RADIATOR AIR GUIDE UPPER CENTRE ? <i>nn</i>	1	\$ 14.00	
46	A/C CONDENSER ? <i>nn</i>	1	\$ 570.00	
47	FRONT WINDOW SLOT SEAL TRIM STRIP - RH X <i>nn</i>	1	\$ 346.00	
48	FRONT WINDOW GUIDE TRIM STRIP - RH X <i>nn</i>	1	\$ 287.00	
49	FRONT WINDOW WATER DEFLECTOR STRIP - RH ? <i>nn</i>	1	\$ 104.00	
50	FRONT NO PLATE <i>st</i> ✓	S/N	\$ 60.00	✓
51	SUNDRIES ? <i>nec</i>		\$ 700.00	5.60 ✓
TOTAL SPARE PARTS		:	\$ 20,277.00	
TOTAL LABOUR CHARGES		:	\$ 13,724.00	
GRAND TOTAL		:	\$ 34,001.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFS 2221 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	/ /
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	250 /
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,500.00	/ /
4	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR.	S/N \$ 380.00	280 /
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	S/N \$ 5,600.00	2750 /
TOTAL LABOUR CHARGES		: \$	8,240.00

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFS 2221 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, HINGES, RHS UPPER A-PILLAR AND RHS FRONT DOOR.	5,000.00 ^{0.80 X 4} S	2200 2200 ✓
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N S 484.00	384 ✓
TOTAL LABOUR CHARGES		: \$ 13,724.00	