

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0729/2022/EQ
DATE : 24-Aug-22
WIP : 38551

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 24/8/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. LOH KOI LEE
ADDRESS : 23 SOMMERVILLE ROAD
#02-05
SINGAPORE 358247
TELEPHONE : HP +65 93676747
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070067312-02
VEHICLE NO : **SFS 2221 U**
MODEL CODE : AUDI A3 SEDAN 1.4 FSI
MODEL YEAR : 30/5/2014
ENGINE NO : CXS 095851
CHASSIS NO : WAUZZZ8V2E1037180
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 12-Aug-22
PLACE OF ACCIDENT : JLN KL-IPOH KM 15

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFS 2221 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00 ✓	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00 250	
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,500.00 ✓	
4	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR.	S/N \$ 380.00 280	
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	5,600.00 2750 S/N \$ 500 x 5.5	
TOTAL LABOUR CHARGES		: \$ 8,240.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFS 2221 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, HINGES, RHS UPPER A-PILLAR AND RHS FRONT DOOR.	<i>0.80 X 4</i> \$ 5,000.00	<i>2200</i>
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 484.00	
TOTAL LABOUR CHARGES		: \$ 13,724.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFS 2221 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>de✓</i>	1	\$	2,377.00
2	FRONT BUMPER FIXING PARTS <i>?</i>	1	\$	195.00
3	FRONT BUMPER TRIM COVER - RH <i>de✓</i>	1	\$	182.00
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>?</i>	1	\$	175.00
5	FRONT BUMPER PULL STRAP LOWER <i>ca✓</i>	<i>AB</i>	\$	231.00
6	FRONT BUMPER GUIDE SECTION - RH <i>?</i>	1	\$	43.00
7	RADIATOR AIR GUIDE GRILLE - RH <i>ms✓</i>	1	\$	122.00
8	RADIATOR GRILLE <i>ca✓</i>	1	\$	765.00
9	RADIATOR GRILLE COVER <i>?</i>	1	\$	109.00
10	FRONT BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$	847.00
11	FRONT BUMPER FOAM FILLER PIECE <i>?</i>	1	\$	154.00
12	FRONT BUMPER REINFORCEMENT BEAM COVER <i>?</i>	1	\$	63.00
13	HORN SIGNAL HIGH TONE- RH <i>?</i>	1	\$	213.00
14	FRONT FENDER - RH <i>ly✓</i>	1	\$	954.00
15	FRONT FENDER ATTACHMENT PARTS <i>?</i>	1	\$	75.00
16	FRONT FENDER BRACET <i>rec✓</i>	1	\$	46.00
17	FRONT FENDER RIVET <i>re✓</i>	6	\$	23.00
18	FRONT FENDER BRACE <i>?</i>	1	\$	107.00
19	FRONT FENDER BRACKET - RH <i>??</i>	1	\$	31.00
20	FRONT WHEEL HOUSING LINER - RH <i>X</i>	1	\$	183.00
SUB TOTAL SPARE PARTS		:	\$	6,895.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFS 2221 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS X	1	\$ 93.00	
22	BONNET <i>buc</i> ✓	1	\$ 3,348.00	
23	BONNET ATTACHMENT PARTS ?	1	\$ 172.00	
24	BONNET HINGE - LH / RH <i>bt</i> ✓	2	\$ 136.00	
25	FRONT BONNET EDGE PROTECTION <i>ne</i> ✓	1	\$ 31.00	
26	BONNET GAS FILLED STRUT ?	1	\$ 110.00	
27	BONNET STRIKER ?	1	\$ 123.00	
28	BONNET LOCK <i>bt</i> ✓	1	\$ 228.00	
29	BONNET CATCH HOOK ?	1	\$ 71.00	
30	BONNET CATCH HOOK ?	1	\$ 100.00	
31	BONNET BOWDEN CABLE ?	1	\$ 64.00	
32	BONNET RELEASE CABLE COVER ?	1	\$ 11.00	
33	HEADLIGHT - RH <i>bro</i> ✓	1	\$ 2,810.00	
34	HEADLIGHT POWER MODULE ?	1	\$ 635.00	
35	GAS DISCHARGE LAMP ?	1	\$ 454.00	
36	HEADLIGHT CONTROL UNIT ?	1	\$ 1,279.00	
37	HEADLIGHT HOSE - RH ?	1	\$ 60.00	
38	LIFT CYLINDER - RH ?	1	\$ 211.00	
39	LIFT CYLINDER HOSE ?	1	\$ 204.00	
40	LOCK CARRIER <i>ca</i> ✓	1	\$ 806.00	
SUB TOTAL SPARE PARTS		:	\$ 10,946.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFS 2221 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	OUTSIDE TEMPERATURE SENSOR BRACKET ?	1	\$ 21.00	
42	READY-MIX COOLANT ✓	6	\$ 297.00	
43	RADIATOR AIR GUIDE - RH ?	1	\$ 28.00	
44	RADIATOR AIR GUIDE OUTER SEAL - RH ?	1	\$ 9.00	
45	RADIATOR AIR GUIDE UPPER CENTRE ?	1	\$ 14.00	
46	A/C CONDENSER ?	1	\$ 570.00	
47	FRONT WINDOW SLOT SEAL TRIM STRIP - RH X	1	\$ 346.00	
48	FRONT WINDOW GUIDE TRIM STRIP - RH X	1	\$ 287.00	
49	FRONT WINDOW WATER DEFLECTOR STRIP - RH ?	1	\$ 104.00	
50	FRONT NO PLATE ✓	S/N	\$ 60.00	
51	SUNDRIES ?		\$ 700.00	
TOTAL SPARE PARTS		:	\$ 20,277.00	
TOTAL LABOUR CHARGES		:	\$ 13,724.00	
GRAND TOTAL		:	\$ 34,001.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME	:	Resur - Hp 90010068
SURVEYED DATE	:	28/08/22 @ 1516
AUTHORISED DATE	:	
EXCESS COST	:	10 days
LIABILITY	:	Revert
REMARKS	:	EXCESS: TBA Resur before paint

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT