

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0729/2022/EQ
DATE : 24-Aug-22
WIP : 38551

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 24/8/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Rasul

10 days exclude 1 Sunday

Johnny Boo 11 Nov 22

OWNER'S NAME : MR. LOH KOI LEE
ADDRESS : 23 SOMMERVILLE ROAD
#02-05
SINGAPORE 358247
TELEPHONE : HP +65 93676747
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070067312-02
VEHICLE NO : **SFS 2221 U**
MODEL CODE : AUDI A3 SEDAN 1.4 FSI
MODEL YEAR : 30/5/2014
ENGINE NO : CXS 095851
CHASSIS NO : WAUZZZ8V2E1037180
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 12-Aug-22
PLACE OF ACCIDENT : JLN KL-IPOH KM 15

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFS 2221 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	\$ 360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	\$ 250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$	1,500.00	\$ 1,500.00
4	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR.	S/N \$	380.00	\$ 280.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	5,600.00	\$ 2,750.00
TOTAL LABOUR CHARGES		:	\$ 8,240.00	\$ 5,140.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFS 2221 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 5,140.00
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, HINGES, RHS UPPER A-PILLAR AND RHS FRONT DOOR.	\$	5,000.00	\$ 2,200.00
7	Added labour	\$	550.00	\$ 550.00
8	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$	484.00	\$ 384.00
TOTAL LABOUR CHARGES		:	\$ 14,274.00	\$ 8,274.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFS 2221 U

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,377.00	\$	1,901.60
2	FRONT BUMPER FIXING PARTS	1	\$ 195.00		
3	FRONT BUMPER TRIM COVER - RH	1	\$ 182.00	\$	145.20
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 175.00		
5	FRONT BUMPER PULL STRAP LOWER	4	\$ 231.00	\$	138.48
6	FRONT BUMPER GUIDE SECTION - RH	1	\$ 43.00		
7	RADIATOR AIR GUIDE GRILLE - RH	1	\$ 122.00	\$	97.20
8	RADIATOR GRILLE	1	\$ 765.00	\$	612.00
9	RADIATOR GRILLE COVER	1	\$ 109.00	\$	87.20
10	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 847.00		
11	FRONT BUMPER FOAM FILLER PIECE	1	\$ 154.00	\$	122.80
12	FRONT BUMPER REINFORCEMENT BEAM COVER	1	\$ 63.00	\$	49.84
13	HORN SIGNAL HIGH TONE- RH	1	\$ 213.00		
14	FRONT FENDER - RH	1	\$ 954.00	\$	763.20
15	FRONT FENDER ATTACHMENT PARTS	1	\$ 75.00		
16	FRONT FENDER BRACET	1	\$ 46.00	\$	36.40
17	FRONT FENDER RIVET	6	\$ 23.00	\$	18.24
18	FRONT FENDER BRACE	1	\$ 107.00	\$	85.60
19	FRONT FENDER BRACKET - RH	1	\$ 31.00	\$	24.24
20	FRONT WHEEL HOUSING LINER - RH	1	\$ 183.00		
SUB TOTAL SPARE PARTS		:	\$ 6,895.00	\$	4,082.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFS 2221 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 4,082.00</i>
21	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1 \$	93.00	
22	BONNET	1 \$	3,348.00	<i>\$ 2,678.40</i>
23	BONNET ATTACHMENT PARTS	1 \$	172.00	
24	BONNET HINGE - LH / RH	2 \$	136.00	<i>\$ 108.48</i>
25	FRONT BONNET EDGE PROTECTION	1 \$	31.00	<i>\$ 24.72</i>
26	BONNET GAS FILLED STRUT	1 \$	110.00	<i>\$ 88.00</i>
27	BONNET STRIKER	1 \$	123.00	
28	BONNET LOCK	1 \$	228.00	<i>\$ 182.00</i>
29	BONNET CATCH HOOK	1 \$	71.00	<i>\$ 56.32</i>
30	BONNET CATCH HOOK	1 \$	100.00	
31	BONNET BOWDEN CABLE	1 \$	64.00	
32	BONNET RELEASE CABLE COVER	1 \$	11.00	
33	HEADLIGHT - RH	1 \$	2,810.00	<i>\$ 2,248.00</i>
34	HEADLIGHT POWER MODULE	1 \$	635.00	<i>\$ 507.60</i>
35	GAS DISCHARGE LAMP	1 \$	454.00	
36	HEADLIGHT CONTROL UNIT	1 \$	1,279.00	<i>\$ 1,023.20</i>
37	HEADLIGHT HOSE - RH	1 \$	60.00	
38	LIFT CYLINDER - RH	1 \$	211.00	
39	LIFT CYLINDER HOSE	1 \$	204.00	
40	LOCK CARRIER	1 \$	806.00	<i>\$ 644.80</i>
SUB TOTAL SPARE PARTS		:	\$ 10,946.00	<i>\$ 11,643.52</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0729/2022/EQ 30-Aug-22 CHANG 1 of 1 SFS 2221 U AUDI A3 SEDAN 1.4 TFSI	
Quantity	Description		Unit Price	Amount
<u>Parts</u>				
1	PLENUM CHAMBER COVER	1	\$ 199.00	\$ 159.20
2	STICKER FOR AIR CONDITIONER	1	\$ 9.00	\$ 6.64
3	SIGN ' CAUTION ' STICKER	1	\$ 16.00	\$ 12.40
GRAND TOTAL			\$ 224.00	\$ 178.24

For Premium Automobiles Pte Ltd

Authorised Signature



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0729/2022/EQ 8-Sep-22 GLORY 1 of 1 SFS 2221 U AUDI A3 SEDAN 1.4 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	TO RESPRAY LHS FRONT FENDER.	\$ 550.00	\$ 550.00
GRAND TOTAL		\$ 550.00	\$ 550.00

For Premium Automobiles Pte Ltd

Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFS 2221 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 11,643.52</i>
41	OUTSIDE TEMPERATURE SENSOR BRACKET	1 \$	21.00	<i>\$ 16.32</i>
42	READY-MIX COOLANT	6 \$	297.00	<i>\$ 237.12</i>
43	RADIATOR AIR GUIDE - RH	1 \$	28.00	<i>\$ 22.16</i>
44	RADIATOR AIR GUIDE OUTER SEAL - RH	1 \$	9.00	
45	RADIATOR AIR GUIDE UPPER CENTRE	1 \$	14.00	
46	A/C CONDENSER	1 \$	570.00	
47	FRONT WINDOW SLOT SEAL TRIM STRIP - RH	1 \$	346.00	
48	FRONT WINDOW GUIDE TRIM STRIP - RH	1 \$	287.00	
49	FRONT WINDOW WATER DEFLECTOR STRIP - RH	1 \$	104.00	
50	FRONT NO PLATE	S/N \$	60.00	<i>\$ 60.00</i>
51	Added parts - see attached	\$	224.00	<i>\$ 178.24</i>
52	SUNDRIES	\$	700.00	<i>\$ 5.60</i>
TOTAL SPARE PARTS			\$ 20,501.00	<i>\$ 12,162.96</i>
TOTAL LABOUR CHARGES			\$ 14,274.00	<i>\$ 8,274.00</i>
GRAND TOTAL			\$ 34,775.00	<i>\$ 20,436.96</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-05/10/22