

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA7976M

DATE 22.08.2022

MAKE REG 28.10.2021

MODEL : HYUNDAI IONIQ G4

CHIANG / NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER <i>CPA</i>			\$481.10 ✓
1	RADIATOR GRILLE <i>CPA</i> X NN			\$1,409.10
1	FRONT BUMPER MOULDING CENTRE UPPER <i>CPA</i>			\$368.50 ✓
1	FRONT BUMPER TOP COVER X NN			\$476.30
2	FRONT HEADLAMP LH/ RH <i>CPA</i>		\$2,110.30 ✓	\$4,220.60
1	FRONT BUMPER GRILLE RH <i>CPA</i>			\$186.90 ✓
1	FRONT DAYLIGHT RH X NN			\$642.50
1	HEAD LAMP PANEL X NN			\$949.30
1	FRONT BUMPER BRACKET LH/RH <i>CPA</i> BR		\$35.00 ✓	\$70.00
1	FRONT FENDER RH <i>CPA</i>			\$588.80
1	FRONT FENDER SHIELD LH/RH X NN		\$164.70	\$329.40
1	FRT FENDER EMBLEM <i>CPA</i>			\$26.60 ✓
1	FRONT RH WHEEL COVER X NN			\$346.40
10	FRONT BUMPER CLIPS <i>CPA</i>			\$22.00 ✓
	SUB TOTAL			\$10,117.50
	20.00%			\$2,023.50
	DISCOUNTED TOTAL			\$8,094.00
1	FRONT NUMBER PLATE W/HOLDER X NN			\$55.00
				\$49.50
	Labour Charge			
	Panel Beating		350	\$900.00
	Spray painting		500	\$800.00
	Check Lighting		30	\$60.00
	TOTAL LABOUR			\$1,760.00
	ESTIMATE TOTAL			\$9,854.49
			3486.72	

2 Days.
45
600 QIP
42 pm
22/8/22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items to be resurveyed and is subject to final approval from Insurance Company

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.