

Our Job Ref No : 305527382  
Date : 27.08.2022

**COMFORTDELGRO**  
**ENGINEERING**

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969

**FINALIZATION FORM**

To : LKK

Fax :

Attn : GUO QIANG

Vehicle Reg No. : SH7976M

22.08.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

|      |                                           |             |                   |
|------|-------------------------------------------|-------------|-------------------|
| Z    | The repair job shall bill to:             | <u>NTUC</u> | <u>GBE9135K</u>   |
| 2.   | The finalized amount shall be:            |             |                   |
| (a)  | Spare Parts after List discount           |             | <u>\$2,606.72</u> |
| (b)  | Labour Charges                            |             | <u>\$880.00</u>   |
|      | <b>Total for Part-By-Part Repair Cost</b> |             | <u>\$3,486.72</u> |
| (c.) | Lumpsum Repair (if applicable)            |             |                   |
|      | Total for Lumpsum repair cost after Less: |             |                   |
|      | <b>Final Lumpsum Repair cost</b>          |             |                   |

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : \_\_\_\_\_

Name : CHIANG

Name : \_\_\_\_\_

Tel : 62148314

Date : \_\_\_\_\_

Fax : 65468156

**For Official Use Only**

| Item                                                 | Amount        | Document Attached Yes or No | Confirm By (Signature) | Remarks |
|------------------------------------------------------|---------------|-----------------------------|------------------------|---------|
| 1. Rental Rate P/Day                                 |               | YES                         |                        |         |
| 2. Loss of Income Paid                               | -             | N                           |                        |         |
| 3. Survey Fees                                       | -             | -                           |                        |         |
| 4. LTA Search Fee                                    | \$7.49/\$2.00 | YES                         |                        |         |
| 5. Medical Fees (on behalf of driver, if applicable) |               |                             |                        |         |
| 6. Overrun                                           |               |                             |                        |         |

Remarks:

\_\_\_\_\_

\_\_\_\_\_

GR/ASH

COMFORTDELGRO ENGINEERING PTE LTD

Date: 24.08.2022

REPAIR ESTIMATE

Time: 13:56:33

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305527382  
REGN NO : SHA7976M  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G3)  
DATE OF REGN : 28.10.2021  
DATE/TIME IN : 22.08.2022 11:10  
ACCIDENT DATE : 22.08.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

|                        |                           |      |          |       |          |      |
|------------------------|---------------------------|------|----------|-------|----------|------|
| 0001 04-01-0104-0578-G | COVER-FR BUMPER#          | 1    | 481.10   | 20.00 | 384.88   |      |
| 0002 04-01-0104-2687-G | MOULDING-FRONT BUMPER CTR | 1    | 368.50   | 20.00 | 294.80   |      |
| 0003 04-01-0104-2686-G | MOULDING-FRONT BUMPER RH  | 1    | 186.90   | 20.00 | 149.52   |      |
| 0004 04-01-0104-3913-G | EMBLEM-BLUE DRIVE RH      | 1    | 26.60    | 20.00 | 21.28    |      |
| 0005 04-01-0101-0111-G | BUMPER COVER CLIP REAR    | 10 L | 22.00    | 20.00 | 17.60    |      |
| 0006 04-01-0104-3918-G | BRACKET-FR BUMPER SIDE RH | 1    | 35.00    | 20.00 | 28.00    |      |
| 0007 04-01-0104-2971-G | BRACKET-FR BUMPER SIDE SU | 1    | 28.00    | 20.00 | 22.40    | ✓ BR |
| 0008 04-01-0104-2935-G | LAMP ASSY-HEAD RH#        | 1    | 2,110.30 | 20.00 | 1,688.24 |      |

SUB-TOTAL : 2,606.72

JOB NATURE

|            |                           |        |
|------------|---------------------------|--------|
| 0000 PB    | PANEL BEATING SHA7976M TP | 350.00 |
| 0001 PB    | PANEL BEATING             | 500.00 |
| 0002 17-01 | CHECK ALL LIGHTING        | 30.00  |

## COMFORTDELGRO ENGINEERING PTE LTD

Date: 24.08.2022

## REPAIR ESTIMATE

Time: 13:56:33

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305527382  
REGN NO : SHA7976M  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G3)  
DATE OF REGN : 28.10.2021  
DATE/TIME IN : 22.08.2022 11:1  
ACCIDENT DATE : 22.08.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 880.00

TOTAL : 3,486.72

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :