

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC2998Y

DATE: 22.08.22

MAKE HYUNDAI

MVA JUMANI

MODEL IONIQ

DOA: 20.08.22

NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY <i>X Repair</i>			\$459.40
1	REAR BUMPER CENTRE MOULDING <i>De</i>			\$451.25
1	REAR BUMPER BEAM <i>nn</i>			\$394.80
10	REAR BUMPER CLIPS <i>X NN</i>			\$22.00
1	REAR FOG LAMP <i>CRA</i>			\$201.50
1	ANTENNA - SMARTKEY <i>nn</i>			\$40.50
SUB TOTAL				\$1,569.45
LESS 20% DISCOUNTED TOTAL				\$1,255.56
REVERSE SENSOR <i>X NN</i>				\$180.00
REAR NUMBER PLATE <i>CRA</i>				\$50.00
BUMPER MAT <i>X NN</i>				\$50.00
Labour Charge				\$280.00
PANEL BEATING				\$400.00
SPRAY PAINT				\$300.00
REMOVE / REFIX REVERSE SENSOR				\$50.00
ADVERTISEMENT LOGO - BUMPER <i>Hand</i>				\$100.00
ADVERTISEMENT LOGO - FENDER				\$200.00
TOTAL LABOUR				\$450.00
ESTIMATE TOTAL				\$2,535.56

✓
✓

NET
NET
NET

250
250
80
11

*22/8/22
45*

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey vehicle after spray painting
- Part of survey is subject to confirmation
- Third party survey is on without prejudice basis
- No illegal modification is allowed
- Supplier's price is subject to resurveyed and is subject to the insurance company

Acknowledged
S

*Caro Qip
22/8/22
3pm*

1200